





report date: 2024-03-28

General information

| Make | FIAT |
|---------------------|-----------------|
| Model | DOBLO 8V ACTIVE |
| Colour | Blue |
| Year of manufacture | 2009 |
| Top speed | 90 mph |
| 0 - 60 mph | 17.0 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 76 BHP |
|-------------------------|---------------------|
| Max. torque | 115 Nm at 3.000 rpm |
| Engine capacity | 1.368 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 30.1 mpg |
| Consumption extra urban | 43.5 mpg |
| Consumption combined | 37.2 mpg |
| CO2 emission | 168 g/km |
| CO2 label | Н |



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-08

Pictures 28

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-09-09 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 12 |
| Failed MOT tests | 3 |
| Total advice items | 6 |
| Total items failed | 3 |

| MOT #15 | 2023-09-05 13:22 |
|------------------|------------------|
| MOT test number | 569638946682 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-09 |

| MOT #14 | 2022-08-31 11:35 |
|-----------------|------------------|
| MOT test number | 773293950368 |
| Result | ✓ Passed |

| MOT #13 | 2022-08-31 11:35 |
|-------------------------|--|
| MOT test number | 143607184628 |
| Result | ★ Failed |
| Pass with rectification | Offside Rear Exhaust silencer likely to become detached (8.1.1 (b) (ii)) |
| Pass with rectification | Seat belt buckle not functioning as intended (7.1.2 (d)) |

| MOT #12 | 2021-09-10 15:28 |
|-----------------|------------------|
| MOT test number | 927407129133 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



MOT #11 2020-12-11 15:59

MOT test number 902739115506

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10 2019-06-08 09:49

MOT test number 404056372797

Result
✓ Passed

MOT #9 2019-06-08 09:07

MOT test number 794059237228

Result X Failed

MAJOR Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #8 2018-05-26 09:00

MOT test number 360186513344

Result
✓ Passed

MOT #7 2017-06-05 11:49

MOT test number 915236516150

Result \rightarrow Passed

MOT #6 2016-06-11 07:56

MOT test number 335500226233

MOT #5 2015-06-04 11:29

MOT test number 618405955106

Result \rightarrow Passed

Notice Nearside rear tyre tread perished.

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #4 2015-06-04 11:29
MOT test number 936825955121

Result × Failed

Pass with rectification Nearside Headlamp aim too high (1.8)

Notice Nearside rear tyre tread perished.

MOT #3 2014-06-12 12:50

MOT test number 129073264109

MOT #2 2013-07-25 11:42

MOT test number 139266303230

Result \rightarrow Passed

Notice N/s/r brake noisey

Notice N/s washer needs cleaning out

MOT #1 2012-08-28 14:04

MOT test number 939081342250

Result
✓ Passed

CarCheck.co.uk page 5/12





report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 337 |
| MOT expiry date | 9 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|------------|
| Band | Н |
| Single payment (12 months) | £ 290,00,- |
| Single six month payment | £ 159,50,- |
| Total payable by 12 monthly instalments | £ 304,50,- |

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

| For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report | |
|--|--|
| | |
| manage of the same | |
| *************************************** | |
| | |
| ******** | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | , |
| Current registration | OK OK |
| Plate since | |
| Current registration | UK NAME OF THE PROPERTY OF THE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Control info | |

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #16

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 16 |
| First mileage registration | 2009-09-29 |
| Last registration | 2023-09-05 |
| Complete history | See info |



| Registration #1 | 2009-09-29 | 6 mi |
|------------------|------------|-----------|
| Registration #2 | 2012-08-28 | 17.104 mi |
| Registration #3 | 2013-07-25 | 22.723 mi |
| Registration #4 | 2014-06-12 | 25.752 mi |
| Registration #5 | 2015-06-04 | 27.431 mi |
| Registration #6 | 2016-06-11 | 27.949 mi |
| Registration #7 | 2017-06-05 | 28.521 mi |
| Registration #8 | 2018-05-26 | 30.037 mi |
| Registration #9 | | 11.177 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.117 es |
| Registration #12 | | 11.117 es |
| Registration #13 | | 11.117 es |
| Registration #14 | | 11.177 es |
| Registration #15 | | 11.177 mi |
| | | |

PRIN. 20. 20

More info >

71.777 mi

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | *** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1722 mm |
|-------------|---------|
| Height | 2073 mm |
| Length | 4253 mm |
| Wheel base | 2583 mm |
| Kerb weight | 1230 kg |

Additional information

| Fuel tank capacity | 60 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles CarCheck.co.uk | 2 page 12/12 |

Engine number

5055820