



report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI XT
Colour	Black
Year of manufacture	2006
Top speed	106 mph
0 - 60 mph	14.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	343 Nm at 1.850 rpm
Engine capacity	2.497 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	204 g/km
CO2 label	K





MOT history

MOT expiry date	2022-09-04
-----------------	------------

MOT pass rate	67 %
---------------	------

MOT passed	12
------------	----

Failed MOT tests	6
------------------	---

Total advice items	19
--------------------	----

Total items failed	16
--------------------	----

MOT #18	2021-09-02 11:06
---------	------------------

MOT test number	729369544764
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2022-09-04
------------------	------------

Advice	Corrosion on rear suspension componets
--------	--

Advice	Rear Suspension component pin or bush slightly worn d bushes (5.3.4 (a) (i))
--------	--

Advice	Front Suspension component pin or bush slightly worn d bushes (5.3.4 (a) (i))
--------	---

MOT #17	2020-09-05 13:54
---------	------------------

MOT test number	363289879517
-----------------	--------------

Result	✓ Passed
--------	----------

Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
--------	---

Minor	Power steering fluid level below minimum (2.1.5 (b) (i))
-------	--

**MOT #16**

2020-09-02 11:00

MOT test number

131622596245

Result

✗ Failed

Minor Power steering fluid level below minimum (2.1.5 (b) (i))**Fail** Nearside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Inner sill area (5.3.6 (a) (i))**Fail** Offside Front Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting Inner sill area (6.2.2 (d) (i))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Offside Rear Suspension component mounting prescribed area excessively corroded significantly reducing structural strength Inner sill area (5.3.6 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #15**

2019-01-30 11:50

MOT test number

103584133271

Result

✓ Passed

MOT #14

2019-01-25 12:59

MOT test number

324556897658

Result

✗ Failed

Fail Offside Parking brake inoperative on one side (1.4.1 (a))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**Fail** Nearside Headlamp aim too low (4.1.2 (a))

**MOT #13** 2018-01-26 10:47**MOT test number** 696346876742**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2017-02-16 16:17**MOT test number** 276954589788**Result** ✓ Passed**MOT #11** 2017-02-03 12:24**MOT test number** 824336603496**Result** ✗ Failed**Fail** Nearside Rear reflector excessively damaged so that its function is impaired (1.5.1c)**Fail** Central Exhaust system not adequately supported (7.1.1)**Fail** Offside Front Upper Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #10** 2016-01-22 12:10**MOT test number** 397450559852**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #9** 2016-01-22 12:10**MOT test number** 692624090729**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2015-02-03 09:36**MOT test number** 977604235089**Result** ✓ Passed**MOT #7** 2015-02-02 16:58**MOT test number** 947153435025**Result** ✗ Failed**Fail** Nearside Rear reflector excessively damaged so that its function is impaired (1.5.1c)**MOT #6** 2013-06-13 11:15**MOT test number** 695214363188**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2012-05-30 12:32**MOT test number** 657961152152**Result** ✓ Passed



MOT #4	2012-05-30 12:32
MOT test number	228441852109
Result	✗ Failed
<div>Pass with rectification</div> Nearside Towbar component insecure (6.6.1)	

MOT #3	2011-06-13 11:52
MOT test number	965454161135
Result	✓ Passed

MOT #2	2010-08-18 09:00
MOT test number	153040430237
Result	✓ Passed

MOT #1	2009-06-13 09:56
MOT test number	430154069107
Result	✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	KV06KDR
Plate since	2019-09-28
Current registration	KV06KDR
Plate since	2019-09-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-06-13
Last registration	2021-09-02
Complete history	See info



Registration #1	2006-06-13	15 mi
Registration #2	2009-06-13	28.973 mi
Registration #3	2010-08-18	44.388 mi
Registration #4	2011-06-13	55.897 mi
Registration #5	2012-05-30	67.154 mi
Registration #6	2013-06-13	78.545 mi
Registration #7	2015-02-02	91.768 mi
Registration #8	2015-02-03	91.768 mi
Registration #9	2016-01-22	100.783 mi
Registration #10	2016-01-22	100.783 mi
Registration #11	2016-01-22	100.783 mi
Registration #12	2016-01-22	100.783 mi
Registration #13	2016-01-22	100.783 mi
Registration #14	2016-01-22	100.783 mi
Registration #15	2016-01-22	100.783 mi
Registration #16	2016-01-22	100.783 mi
Registration #17	2016-01-22	100.783 mi
Registration #18	2016-01-22	100.783 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1804 mm
Length	4567 mm
Wheel base	2710 mm
Kerb weight	2056 kg
Max. allowed weight	2600 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4CB5878441