





report date: 2024-03-28

General information

Make	FIAT
Model	DOBLO 16V MULTIJET
Colour	Red
Year of manufacture	2016
Top speed	102 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	290 Nm at 1.500 rpm
Engine capacity	1.598 сс
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	144 g/km
CO2 label	F



CarCheck.co.uk page 1/11



BL16WLX

report date: 2024-03-28

Internet history

Entry 2

Date 2023-03-08

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-06-25
Pictures	10

11000100

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



BL16WLX

report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2024-10-12
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	8
Total items failed	0

MOT #5	2023-10-13 12:56
MOT test number	613673830058
Result	✓ Passed
Next expiry date	2024-10-12

MOT #4	2022-10-13 13:26
MOT test number	352610768620
Result	✓ Passed

MOT #3	2022-10-12 11:13
MOT test number	972524482656

Result X Failed

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))

MAJOR Rear Service brake lagging in operation (1.2.1 (d))

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2	2020-09-11 07:35
MOT test number	482857887702
Result	✓ Passed
Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/11



BL16WLX

report date: 2024-03-28

MOT #1 2019-06-03 08:39

MOT test number 742698474023

Result ✓ Passed

Advice Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Offside Front Upper Macpherson strut mounting corroded but not seriously weakened and mounting bearing is rough in operation from left to right (5.3.3 (b) (i))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	12 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

e union mestery		
For how long did the current and previous owner(s) have this FIAT? How many owners did Check it in the premium report and see all owner registrations. Download the full report is		e?
THE PARTY OF THE P		

THE STREET STREE		
	More info	>
Plate changes		
See in this check if this FIAT had different number plates.		
Number of plates		,
Current registration	OK SIE	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-07-12
Last registration	2023-10-13
Complete history	See info



Registration #1	2016-07-12	11 mi
Registration #2	2019-06-03	30.147 mi
Registration #3	2020-09-11	52.944 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditionin
S0295	
S0482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1832 mm
Height	1845 mm
Length	4390 mm
Kerb weight	1445 kg
Max. allowed weight	2465 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	7611922

CarCheck.co.uk page 11/11