





report date: 2024-03-28

General information

Make	MERCEDES-BENZ
Model	SPRINTER 313 CDI
Colour	Silver
Year of manufacture	2013
Top speed	95 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	95 kW / 129 HP / 129 BHP
Max. torque	305 Nm at 1.200 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	38.2 mpg
CO2 emission	213 g/km
CO2 label	K



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date 2021-06-29

Pictures 6

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2023-08-04
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	25
Total items failed	4

MOT #10		2022-08-03 12:20
MOT test	MOT test number 6376964973	
Result		✓ Passed
Next exp	iry date	2023-08-04
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Advice Offside Front Lower Suspension component ball joint has slight play up lift (5.3.4 (a) (i))	
Minor Nearside Rear Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))		
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
Advice	Advice Nearside Front accident damages	
Minor (i))	Nearside Side repeater lens defective which has no effect on emitted ligh	nt lens damaged (4.4.1 (b)

MOT #9	2021-08-05 13:40
MOT test number	404529347831
Result	✓ Passed
Advice Advise wear to front off side tyre and slight play in front wheel bearing	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #8 2021-07-30 11:00

MOT test number 180554413155

Result X Failed

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Advise wear to front off side tyre and slight play in front wheel bearing

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MOT #7 2020-11-05 09:38

MOT test number 726922871321

Result ✓ Passed

Minor Nearside Obligatory mirror slightly damaged mirror glass cracked (3.3 (b) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge feathering on edges of tread (5.2.3 (e))

Advice Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice Nearside Rear Nail in tyre

Advice Nearside Front Tyre worn close to legal limit/worn on edge approx. 2mm (235/65r16c) inner edge of tread worn badly (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge approx. 3mm (5.2.3 (e))

Advice Vehicles internal headlight adjuster altered to recheck lights

CarCheck.co.uk page 4/12



Advice

Advice

LO63VBN

report date: 2024-03-28

MOT #6 2020-11-05 09:38 549483355022 **MOT** test number Result × Failed **Advice** Nearside Front Tyre worn close to legal limit/worn on edge approx. 2mm (235/65r16c) inner edge of tread worn badly (5.2.3 (e)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge approx. 3mm (5.2.3 (e)) Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a)) **Advice** Nearside Rear Nail in tyre **Advice** Offside Front Tyre worn close to legal limit/worn on edge feathering on edges of tread (5.2.3 (e)) Minor Nearside Obligatory mirror slightly damaged mirror glass cracked (3.3 (b) (i))

MOT #5

MOT test number

Result

Advice Offside Front Road wheel slightly distorted outer rim (5.2.2 (c) (i))

Vehicles internal headlight adjuster altered to recheck lights

Offside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT test number

Result

Advice Offside Front Road wheel slightly distorted outer rim (5.2.2 (c) (i))

Fail Offside Rear reflector missing (4.8.2 (a) (ii))

 MOT #3
 2018-11-19 16:01

 MOT test number
 593150704871

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

MOT #2

MOT test number

Result

Advice Offside Front tyre wearing on inner edge

MOT #1	2016-11-23 09:56
MOT test number	151061607966
Result	✓ Passed

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra MERCEDES-BENZ salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How ma MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. I report here .	

Plate changes	More info >
See in this check if this MERCEDES-BENZ had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-12-31
Last registration	2022-08-03
Complete history	See info



Registration #1	2013-12-31	14 mi
Registration #2	2016-11-23	27.310 mi
Registration #3	2017-11-07	36.616 mi
Registration #4	2018-11-19	45.942 mi
Registration #5	2019-11-11	54.157 mi
Registration #6	2019-11-12	54.157 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

60225	Air conditionin
60295	
0482	
0501	
0566	
0567	
0569	
iew the complete MERCEDES-BENZ factory list for this	More info >

Dimensions & weight

Width	1993 mm
Height	2700 mm
Length	6945 mm
Wheel base	4325 mm
Kerb weight	2414 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	100
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Number of axles	2
Engine number	65195531931237

CarCheck.co.uk page 12/12