





report date: 2024-03-28

## General information

Make	RENAULT
Model	TRAFIC SL27 DCI S/R P/V
Colour	Silver
Year of manufacture	2013
Top speed	99 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.9 mpg
CO2 emission	180 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-28

## Internet history

#### Entry 2

Date 2021-12-18

Pictures 15

Listing price <u>View report</u>









source: yesauto.com

#### Entry 1

Date	2021-12-01	
Pictures	1	
Listing price	View report	



source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-07
MOT pass rate	80 %
MOT passed	8
Failed MOT tests	2
Total advice items	15
Total items failed	6

MOT #10	2024-03-06 11:00
MOT test number	196515190755
Result	✓ Passed
Next expiry date	2025-03-07

MOT #9		2023-03-08 14:19
MOT test	number	398407355420
Result		<b>✓</b> Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated,	but preventing the
ingress of dirt (2.1.3 (g) (i))		

MOT #8	2022-02-16 17:09
MOT test number	260840625971
Result	<b>✓</b> Passed

MOT #7	2020-10-23 10:32
MOT test number	653123049454
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

**MOT** #6 2020-10-19 10:49 759417268966 **MOT** test number Result × Failed **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Nail in tyre Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h)) Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail **Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i)) **Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) Fail

MOT #5	2019-10-08 08:42
MOT test number	498230257844
Result	<b>✓</b> Passed

MOT #4		2018-10-04 09:27
MOT test	number	410683171087
Result		✓ Passed
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Nail in tyre	

CarCheck.co.uk page 4/12



report date: 2024-03-28



MOT #2	2017-09-29 10:35
MOT test number	198687210556
Result	✓ Passed
MOT #1	2016 06 22 14:17

MOT #1	2016-06-22 14:17	7
MOT test	number 414322414896	;
Result	✓ Passed	ı
Advice	Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	7 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

More info >

# Owner history For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this RENAULT had different number plates. ober of plates faste since

CarCheck.co.uk page 9/12



#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-25
Last registration	2024-03-06
Complete history	See info



Registration #1	2013-03-25	21 mi
Registration #2	2016-06-22	23.783 mi
Registration #3	2017-09-29	31.819 mi
Registration #4	2018-10-04	39.343 mi
Registration #5	2018-10-04	39.343 mi
Registration #6	2019-10-08	47.068 mi
Registration #7	2020-10-19	53.750 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		0.074

More info >

CarCheck.co.uk page 11/12



Car features

50225	Air conditionir
60295	
60482	
60501	
60566	
0567	
0569	

# Safety ratings

NCAP rating	******
Adult	58%
Children	79%
Pedestrian	28%
Safety systems	14%
Overall rating	51%
Video	see crash video



## Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	C036427

CarCheck.co.uk page 12/12