





report date: 2024-03-29

General information

| Make | VAUXHALL |
|---------------------|----------------|
| Model | GRANDLAND |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 117 mph |
| 0 - 60 mph | 9.5 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 128 BHP |
|----------------------|---------------------|
| Max. torque | 230 Nm at 1.750 rpm |
| Engine capacity | 1.199 сс |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption combined | 44.1 mpg |
| CO2 emission | 117 g/km |
| CO2 label | С |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-10

Pictures 18

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

| MOT expiry date | 2024-09-01 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 11 |
| Total items failed | 0 |

| MOT #5 | | 2023-08-29 09:56 |
|-----------|--|--------------------|
| MOT test | number | 124479940363 |
| Result | | ✓ Passed |
| Next expi | y date | 2024-09-01 |
| Advice | Brake pedal wearing smooth Rubber missing but the pedal surface is g | rooved (1.1.2 (c)) |
| Advice | Front Both front wipers smearing | |

| MOT #4 | | 2023-08-26 10:47 |
|--|--|----------------------|
| MOT test | number | 832905225570 |
| Result | | 🗙 Failed |
| Advice | Front Both front wipers smearing | |
| MAJOR | Offside Front Suspension arm pin or bush excessively worn Rear bush bond | ding (5.3.4 (a) (i)) |
| MAJOR Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords On tread pattern (5.2.3 (d) (i)) | | |
| Advice | Brake pedal wearing smooth Rubber missing but the pedal surface is groov | ved (1.1.2 (c)) |

CarCheck.co.uk page 3/11



report date: 2024-03-29

| MOT #3 | | 2022-09-01 14:52 |
|----------|---|------------------|
| MOT test | number | 270141263936 |
| Result | | ✓ Passed |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge 225/55/18 (5.2.3 (e)) | |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Signs of oil leak on sump tray | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge 225/55/18 (5.2.3 (e)) | |

| MOT #2 | 2021-09-02 13:28 |
|--|------------------|
| MOT test number | 376038751473 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2021-01-23 11:55 |
| MOT test number | 419342093290 |
| Result | ✓ Passed |
| Advice Rear Child Seat fitted not allowing full inspection of adult belt | |

CarCheck.co.uk page 4/11



Tax & MOT check





Expires: 1 September 2024

| Tax status | Valid until 1 November |
|------------------|------------------------|
| Days left | 186 |
| MOT expiry date | 1 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

More info >

Owner history

| • | |
|---|-------------|
| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloahere. | |
| | |
| *************************************** | |
| | |
| | |
| | |
| *************************************** | |
| Plate changes | More info > |
| See in this check if this VAUXHALL had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | UK UK |
| Plate since | |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-01-31 |
| Last registration | 2023-08-29 |
| Complete history | See info |



| Registration #1 | 2018-01-31 | 18 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-01-23 | 19.056 mi |
| Registration #3 | 2021-09-02 | 21.816 mi |
| Registration #4 | | 71.777 es |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11,177 es |

More info >

CarCheck.co.uk page 10/11



Safety ratings

| NCAP rating | **** | |
|----------------|-----------------|--|
| Adult | 84% | |
| Children | 87% | |
| Pedestrian | 63% | |
| Safety systems | 60% | |
| Overall rating | 76% | |
| Video | see crash video | |



Dimensions & weight

| Width | 1856 mm |
|---------------------|---------|
| Height | 1609 mm |
| Length | 4477 mm |
| Wheel base | 2675 mm |
| Kerb weight | 1350 kg |
| Max. allowed weight | 1910 kg |

Additional information

| Fuel tank capacity | 53 I |
|--------------------|-------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 10XTA11015104 LES |

CarCheck.co.uk page 11/11