



report date: 2024-03-29

General information

Make	FIAT
Model	PUNTO ACTIVE
Colour	Grey
Year of manufacture	2010
Top speed	103 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-05-28
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-29
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	65
Total items failed	2

MOT #15	2023-08-29 12:44
MOT test number	673162558445
Result	✓ Passed
Next expiry date	2024-08-29

MOT #14	2023-08-29 11:36
MOT test number	218985552773
Result	✗ Failed
MAJOR Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #13	2022-08-30 17:24
MOT test number	692490349073
Result	✓ Passed

**MOT #12**

2022-02-26 10:26

MOT test number

944152858271

Result

✓ Passed

- Advice** Exhaust silencer slightly loose exhaust skin rotted and loose (8.1.1 (b) (i))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front inner discs (1.1.14 (a) (ii))
- Advice** Exhaust has a minor leak of exhaust gases front flexi section has small leak (6.1.2 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Coil spring corroded both rear (5.3.1 (b) (i))
- Advice** Direction indicator slightly discoloured both rear indicators starting flash white (4.4.3 (a))

MOT #11

2022-02-26 10:26

MOT test number

118516472683

Result

✗ Failed

- Pass with rectification** Offside Front Headlamp aim too high and too far to the right. (4.1.2 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases front flexi section has small leak (6.1.2 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Coil spring corroded both rear (5.3.1 (b) (i))
- Advice** Direction indicator slightly discoloured both rear indicators starting flash white (4.4.3 (a))
- Pass with rectification** Headlamp incorrect colour (4.1.4 (a))
- Advice** Exhaust silencer slightly loose exhaust skin rotted and loose (8.1.1 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened both front inner discs (1.1.14 (a) (ii))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

**MOT #10**

2021-02-26 11:51

MOT test number

545384236622

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn /Perished. (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Exhaust system corroded.
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9

2021-02-25 15:12

MOT test number

694126689946

Result

✗ Failed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Front Registration plate inscription illegible (0.1 (b))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn /Perished. (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust system corroded.

**MOT #8**

2020-02-24 17:15

MOT test number

999619931026

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Lipped. (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Exhaust corroded.
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (Perished/Cracking). (5.2.3 (d) (ii))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (Perished/Cracking). (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #7**

2020-02-24 11:55

MOT test number

272517554424

Result**✗ Failed**

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (Perished/Cracking). (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (Perished/Cracking). (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Lipped. (1.1.14 (a) (ii))
- Advice** Exhaust corroded.
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #6

2019-02-19 11:51

MOT test number

988295684173

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear exhaust corroded
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #5** 2018-02-26 12:08**MOT test number** 874864053690**Result** ✓ Passed**MOT #4** 2016-08-18 15:05**MOT test number** 420966143256**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2015-07-31 09:23**MOT test number** 408152215219**Result** ✓ Passed**Notice** Rear exhaust corroded**MOT #2** 2014-07-14 15:58**MOT test number** 247245394459**Result** ✓ Passed**MOT #1** 2013-05-28 09:55**MOT test number** 708738343106**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
29 August 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	29 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history


Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-29
Last registration	2023-08-29
Complete history	See info



Registration #1	2010-05-29	12 mi
Registration #2	2013-05-28	17.183 mi
Registration #3	2014-07-14	22.343 mi
Registration #4	2015-07-31	28.121 mi
Registration #5	2016-08-18	36.943 mi
Registration #6	2018-02-26	41.022 mi
Registration #7	2019-02-19	48.943 mi
Registration #8	2020-02-24	53.916 mi
Registration #9	2020-02-24	53.916 mi
Registration #10	2020-02-24	53.916 mi
Registration #11	2020-02-24	53.916 mi
Registration #12	2020-02-24	53.916 mi
Registration #13	2020-02-24	53.916 mi
Registration #14	2020-02-24	53.916 mi
Registration #15	2020-02-24	53.916 mi
Registration #16	2020-02-24	53.916 mi
Registration #17	2020-02-24	53.916 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	5839116