





report date: 2024-03-29

# General information

Make	RENAULT
Model	ZOE DYNAMIQUE NAV
Colour	White
Year of manufacture	2018
Top speed	84 mph
0 - 60 mph	11.9 seconds
Gearbox	1 speed automatic

# Engine & fuel consumption

Power	108 BHP
Max. torque	225 Nm at 3.395 rpm
Fuel type	Electricity
Consumption combined	235.2 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-29

# Internet history

# Entry 1

Date 2021-02-04

Pictures 3

Listing price <u>View report</u>







source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

MOT expiry date	2025-02-04
MOT pass rate	50 %
MOT passed	2
Failed MOT tests	2
Total advice items	12
Total items failed	4

MOT #4	2024-02-05 10:05
MOT test number	725458345100
Result	✓ Passed
Next expiry date	2025-02-04
Advice Nearside Front Tyre slightly damaged/cracking or perishing has damage to the outer sidewall (5.2.3 (d) (ii))	

MOT #3	2023-12-29 08:30
MOT test number	754356473585
Result	<b>×</b> Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice Offside Rear Nail in tyre	
Advice Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number
674729633216

Result

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #1** 2022-11-10 13:50 **MOT** test number 125596316767 Result × Failed Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i)) Fail

CarCheck.co.uk page 4/11



report date: 2024-03-29

# Tax & MOT check





Tax status Expired at 3 July 2020

Days left 1396 days too late

MOT expiry date 4 February 2025

Full MOT history See MOT history

CarCheck.co.uk page 5/11



report date: 2024-03-29

# Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

# **SK67NHA**

report date: 2024-03-29

# For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here">here</a>. More info >

# Plate changes

See in this check if this RENAULT had different number plates.

\*\*\*The company of the company of

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

# Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-01-31
Last registration	2024-02-05
Complete history	See info



Registration #1	2018-01-31	27 mi
Registration #2		71,777 es
Registration #3	2022-11-10	28.371 mi
Registration #4		11,777 es
Registration #5		71,777 66
Registration #6		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



# Dimensions & weight

Width	1945 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1500 kg
Max. allowed weight	1954 kg

# Additional information

Fuel delivery	Not Applicable	
Number of doors	5	
Number of seats	5	
Number of axles Carcheck.co.uk	2	page 11/11