



report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Blue
Year of manufacture	-
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	331 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-01-08
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #19	2022-01-19 15:54
MOT test number	101893470764
Result	✓ Passed
Next expiry date	2023-01-18
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
Advice	Rear Fuel Pipe/s corroded
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #18	2022-01-13 11:20
MOT test number	297503519683
Result	✗ Failed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Rear Fuel Pipe/s corroded
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Front Headlamp aim too low (4.1.2 (a))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Fail	Offside Front Driver's door cannot be opened from outside the vehicle (6.2.3 (a))
Fail	Nearside Front Headlamp aim too low (4.1.2 (a))
Advice	Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #17** 2021-01-13 09:48**MOT test number** 741409025651**Result** ✓ Passed**MOT #16** 2020-01-09 09:40**MOT test number** 692628381052**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #15** 2019-01-08 13:55**MOT test number** 396739517288**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #14** 2019-01-07 11:27**MOT test number** 988441726344**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #13** 2017-12-18 11:46**MOT test number** 105861120185**Result** ✓ Passed

**MOT #12** 2016-11-02 09:50**MOT test number** 858468192278**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit 225/45/17 (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 225/45/17 (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #11** 2016-11-02 09:50**MOT test number** 232989452039**Result** ✗ Failed**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit 225/45/17 (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit 225/45/17 (4.1.E.1)**Advice** Parking brake lever has little reserve travel (3.1.6b)**MOT #10** 2015-11-14 13:34**MOT test number** 768953958145**Result** ✓ Passed**MOT #9** 2014-11-19 16:29**MOT test number** 567453124359**Result** ✓ Passed**MOT #8** 2014-04-04 12:26**MOT test number** 889424794010**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #7	2013-03-14 11:44
---------------	------------------

MOT test number	336833973069
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2012-03-23 12:06
---------------	------------------

MOT test number	129643482087
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2011-03-29 11:51
---------------	------------------

MOT test number	406108281011
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2010-03-17 13:40
---------------	------------------

MOT test number	430356070042
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2009-03-18 10:49
---------------	------------------

MOT test number	822697879019
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)
---------------	---

Notice	Slight play to nearside of steering rack arm
---------------	--

Notice	Nearside rear tyre outer tread worn low and unevenly, recommend renewal of tyre
---------------	---

MOT #2	2008-03-13 14:09
---------------	------------------

MOT test number	210443878018
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #1	2008-03-13 10:46
MOT test number	751643278063
Result	✗ Failed
Fail	Offside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
Notice	Nearside front tyre inner tread to shoulder partly worn low,possible may cause a lump like offside front tyre,recommend renewal of tyre as soon as possible



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	BF05JKK
Plate since	2024-03-29
Current registration	BF05JKK
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2005-03-01
Last registration	2022-01-19
Complete history	See info



Registration #1	2005-03-01	20 mi
Registration #2	2008-03-13	19.845 mi
Registration #3	2008-03-13	19.848 mi
Registration #4	2009-03-18	27.453 mi
Registration #5	2010-03-17	34.393 mi
Registration #6	2011-03-29	41.951 mi
Registration #7	2012-03-23	48.554 mi
Registration #8	2013-03-14	55.722 mi
Registration #9	2014-04-04	61.356 mi
Registration #10	2014-11-19	66.480 mi
Registration #11	2015-11-14	81.784 mi
Registration #12	2016-01-20	91.277 mi
Registration #13	2016-02-26	91.277 mi
Registration #14	2016-03-26	91.277 mi
Registration #15	2016-04-26	91.277 mi
Registration #16	2016-05-26	91.277 mi
Registration #17	2016-06-26	91.277 mi
Registration #18	2016-07-26	91.277 mi
Registration #19	2016-08-26	91.277 mi
Registration #20	2016-09-26	91.277 mi
Registration #21	2016-10-26	91.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Kerb weight	1575 kg
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	0502040858226G