



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	PASSAT HIGHLINE TDI
Colour	Black
Year of manufacture	2009
Top speed	119 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.986 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	62.8 mpg
Consumption combined	51.4 mpg
CO2 emission	143 g/km
CO2 label	F





MOT history

MOT expiry date	2024-10-24
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	27
Total items failed	0

MOT #15	2023-10-25 09:45
MOT test number	194538552349
Result	✓ Passed
Next expiry date	2024-10-24
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #14	2023-10-11 16:43
MOT test number	710172346898
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Nearside Front Service brake excessively binding (1.2.1 (f))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
MAJOR	Driver's door cannot be opened from outside the vehicle (6.2.3 (a))

MOT #13	2022-09-03 09:40
MOT test number	949071901839
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #12** 2022-09-02 14:48**MOT test number** 305398557540**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Front Suspension arm pin or bush excessively worn 2x bothsides (5.3.4 (a) (i))**MOT #11** 2021-08-27 16:02**MOT test number** 937804427185**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2020-11-16 14:02**MOT test number** 979706702634**Result** ✓ Passed**MOT #9** 2019-09-06 13:55**MOT test number** 817570985260**Result** ✓ Passed**MOT #8** 2018-06-14 10:24**MOT test number** 739444399125**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

**MOT #7** 2018-06-13 13:55**MOT test number** 886495191461**Result** ✗ Failed

MAJOR Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MAJOR Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #6 2017-06-14 13:56**MOT test number** 203552478039**Result** ✓ Passed

Advice Offside Front Inner Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Front Inner Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5 2016-06-15 10:05**MOT test number** 846855793346**Result** ✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #4 2015-06-22 11:42**MOT test number** 256933675192**Result** ✓ Passed

**MOT #3** 2014-10-28 10:28**MOT test number** 329551104309**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #2** 2013-11-18 08:42**MOT test number** 877012423365**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nail in nearside rear tyre**MOT #1** 2012-08-13 12:16**MOT test number** 995226722286**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
24 October 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	24 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 CV59RJO
Plate since	2024-03-29
Current registration	 CV59RJO
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-14
Last registration	2023-10-25
Complete history	See info



Registration #1	2009-09-14	27 mi
Registration #2	2012-08-13	18.991 mi
Registration #3	2013-11-18	36.147 mi
Registration #4	2014-10-28	50.706 mi
Registration #5	2015-06-22	58.827 mi
Registration #6	2016-06-15	73.038 mi
Registration #7	2017-06-14	83.752 mi
Registration #8	2018-06-13	94.547 mi
Registration #9	2019-06-13	105.342 mi
Registration #10	2020-06-13	116.137 mi
Registration #11	2021-06-13	126.932 mi
Registration #12	2022-06-13	137.727 mi
Registration #13	2023-06-13	148.522 mi
Registration #14	2024-06-13	159.317 mi
Registration #15	2025-06-13	170.112 mi
Registration #16	2026-06-13	180.907 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1435 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBD 173871