



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO GP
Colour	Black
Year of manufacture	2011
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	132 g/km
CO2 label	E






Internet history

Entry 2

Date	2021-09-04
Pictures	15
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-02
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-21
MOT pass rate	55 %
MOT passed	11
Failed MOT tests	9
Total advice items	72
Total items failed	26

MOT #20	2023-12-22 13:44
MOT test number	990654972603
Result	✓ Passed
Next expiry date	2024-12-21
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #19	2023-12-22 13:44
MOT test number	774237075415
Result	✗ Failed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #18**

2023-01-17 10:07

MOT test number

495646925082

Result

✓ Passed

- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Central Rear underbody corrosion
- Advice** Offside Front Side repeater slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Minor** Nearside Front Windscreen excessively tinted but not adversely affecting driver's view crack in passenger swept area (3.2 (b) (i))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Central Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Front Side repeater slightly discoloured (4.4.3 (a))



MOT #17

2023-01-16 09:39

MOT test number

606480518880

Result

✗ Failed

- Fail** Offside Front Direction indicator incorrect colour (4.4.3 (a))
- Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Nearside Front Windscreen excessively tinted but not adversely affecting driver's view crack in passenger swept area (3.2 (b) (i))
- Minor** Offside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Side repeater slightly discoloured (4.4.3 (a))
- Fail** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Front Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Side repeater slightly discoloured (4.4.3 (a))
- Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- Fail** Offside Rear Entrance/exit door defective in operation wont open from outside (9.1.1 (a))
- Advice** Central Front Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Central Rear underbody corrosion
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #16**

2022-01-24 15:49

MOT test number

804827620739

Result

✓ Passed

Advice Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**Advice** Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Coil spring corroded (5.3.1 (b) (i))**MOT #15**

2022-01-22 15:41

MOT test number

210628922697

Result

✗ Failed

Advice Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))**Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Exhaust emissions likely to be affected by an exhaust leak emission not tested (8.2.2.1 (b))**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #14**

2021-01-13 14:09

MOT test number

137192831274

Result

✓ Passed

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Oil leak
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Macpherson strut damaged but not seriously weakened (5.3.3 (b) (i))

MOT #13

2021-01-12 12:56

MOT test number

142242136791

Result

✗ Failed

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak
- Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Front Macpherson strut damaged but not seriously weakened (5.3.3 (b) (i))
- Fail** Fuel cap/sealing device ineffective (6.1.3 (b) (i))

**MOT #12**

2020-01-10 12:40

MOT test number

488126215050

Result

✓ Passed

- Advice** Oil leak
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #11

2020-01-10 09:57

MOT test number

837307459080

Result

✗ Failed

- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Oil leak
- Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))

**MOT #10** 2019-01-11 15:04**MOT test number** 460511543339**Result** ✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Exhaust has a minor leak of exhaust gases back box. exhaust system corroded (6.1.2 (a))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Oil leak, but not excessive gearbox (8.4.1 (a) (i))
- Advice** Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #9 2018-01-03 16:27**MOT test number** 161290402564**Result** ✓ Passed**MOT #8** 2018-01-03 10:00**MOT test number** 839507207205**Result** ✗ Failed

- Fail** Nearside Front coil spring broken (2.4.C.1a)
- Fail** Offside Front coil spring broken (2.4.C.1a)

MOT #7 2017-01-06 16:56**MOT test number** 792846230737**Result** ✓ Passed

**MOT #6** 2017-01-06 09:14**MOT test number** 283760873125**Result** ✗ Failed

- Fail** Offside Front coil spring broken (2.4.C.1a)
- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Fail** Offside Front Steering system has a tyre fouling a part of the vehicle (2.2.D.2a)

MOT #5 2016-01-12 10:49**MOT test number** 554733348259**Result** ✓ Passed

- Advice** Rear silencer outer skin corroding

MOT #4 2016-01-08 15:24**MOT test number** 645583307812**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Rear silencer outer skin corroding
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Headlamp not working on dipped beam (1.7.5a)

MOT #3 2015-01-08 13:02**MOT test number** 786028605097**Result** ✓ Passed**MOT #2** 2015-01-08 12:11**MOT test number** 945668705031**Result** ✗ Failed

- Fail** Rear Direction indicators incorrect colour (1.4.A.2f)



MOT #1	2014-03-14 11:29
MOT test number	857283574083
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
21 December 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	21 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2011-03-25
Last registration	2023-12-22
Complete history	See info



Registration #1	2011-03-25	24 mi
Registration #2	2014-03-14	21.000 mi
Registration #3	2015-01-08	24.017 mi
Registration #4	2015-01-08	24.017 mi
Registration #5	2016-01-08	39.664 mi
Registration #6	2016-01-12	39.684 mi
Registration #7	2017-01-06	51.773 mi
Registration #8	2017-01-06	51.773 mi
Registration #9	2018-01-03	61.898 mi
Registration #10	2018-01-03	61.898 mi
Registration #11	2019-01-11	73.178 mi
Registration #12	2020-01-10	79.668 mi
Registration #13	2020-01-10	79.668 mi
Registration #14	2020-01-10	79.668 mi
Registration #15	2020-01-10	79.668 mi
Registration #16	2020-01-10	79.668 mi
Registration #17	2020-01-10	79.668 mi
Registration #18	2020-01-10	79.668 mi
Registration #19	2020-01-10	79.668 mi
Registration #20	2020-01-10	79.668 mi
Registration #21	2020-01-10	79.668 mi
Registration #22	2020-01-10	79.668 mi
Registration #23	2020-01-10	79.668 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6339707