



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	White
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-08-07
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-06
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	16
Total items failed	10

MOT #15	2023-07-31 15:44
MOT test number	276686941430
Result	✓ Passed
Next expiry date	2024-08-06
Advice	Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #14**

2023-07-31 09:42

MOT test number

824738465010

Result**✗ Failed**

- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Anti-roll bar linkage fractured drop link broken (5.3.3 (b) (ii))
- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on edges (5.2.3 (e))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords worn inner edge (5.2.3 (d) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #13

2022-08-02 08:40

MOT test number

479279708977

Result**✓ Passed****MOT #12**

2022-08-02 08:40

MOT test number

695610335493

Result**✗ Failed**

- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #11

2021-08-07 10:30

MOT test number

935923560640

Result**✓ Passed**

**MOT #10** 2020-11-17 13:43**MOT test number** 345744703070**Result** ✓ Passed**Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #9** 2020-11-17 13:43**MOT test number** 237828455882**Result** ✗ Failed**Advice** Nearside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #8** 2019-11-21 16:26**MOT test number** 130135481198**Result** ✓ Passed**MOT #7** 2019-11-20 14:10**MOT test number** 593465035088**Result** ✗ Failed**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #6** 2018-10-23 14:56**MOT test number** 890725168123**Result** ✓ Passed

**MOT #5** 2018-10-23 14:56**MOT test number** 256061861650**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #4** 2017-11-13 11:12**MOT test number** 311082658741**Result** ✓ Passed**MOT #3** 2017-02-17 13:04**MOT test number** 641219874608**Result** ✓ Passed**MOT #2** 2016-02-24 16:35**MOT test number** 992089022078**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #1** 2016-02-24 16:35**MOT test number** 418740250430**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
6 August 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	6 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 MF13YUY
Plate since	2019-06-29
Current registration	 MF13YUY
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2013-03-14
Last registration	2023-07-31
Complete history	See info



Registration #1	2013-03-14	20 mi
Registration #2	2016-02-24	14.937 mi
Registration #3	2016-02-24	14.937 mi
Registration #4	2017-02-17	21.545 mi
Registration #5	2017-11-13	26.886 mi
Registration #6	2018-10-23	34.567 mi
Registration #7	2018-10-23	34.567 mi
Registration #8	2019-11-20	43.525 mi
Registration #9	2019-11-21	43.525 mi
Registration #10	2020-05-20	55.377 mi
Registration #11	2020-05-20	55.377 mi
Registration #12	2020-05-20	55.377 mi
Registration #13	2020-05-20	55.377 mi
Registration #14	2020-05-20	55.377 mi
Registration #15	2020-05-20	55.377 mi
Registration #16	2020-05-20	55.377 mi
Registration #17	2020-05-20	55.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ