





report date: 2024-03-29

#### General information

Make	RENAULT
Model	MEGANE EXPRESSION PLUS DCI
Colour	Silver
Year of manufacture	2013
Top speed	118 mph
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg
CO2 emission	90 g/km
CO2 label	A



CarCheck.co.uk page 1/13



## Internet history

#### Entry 1

Date	2021-02-04
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

### **MOT** history

MOT expiry date	2024-04-19
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	31
Total items failed	15

MOT #3	<b>‡12</b> 2024-04	-22 13:26
MOT te	est number 26930	04641555
Result		<b>X</b> Failed
Fail	Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))	
Advic	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail	Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Mino	Rear Windscreen wiper blade defective (3.4 (b) (i))	
Advic	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
<b>Advic</b> (4.4.3 (		ulb
Fail	Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Fail	Rear Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))	
Advic	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail is 1.0m	Offside Rear Tyre tread pattern not visible over the whole tread area when minimum depth renm (5.2.3 (e))	equired
Fail	Offside Front Headlamp aim unable to be tested (4.1.2 (b))	
Fail	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail	Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))	

CarCheck.co.uk page 3/13



Result

HV63ZKA

report date: 2024-03-29

**MOT #11** 2023-04-13 14:31

**MOT** test number 954332618616

✓ Passed

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2.0mm (5.2.3 (e))

Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i)) Advice

Offside Rear Service brake binding but not excessively (1.2.1 (f)) **Advice** 

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10** 2023-04-13 08:25

**MOT** test number 630652383141

Result ★ Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Brake disc worn, pitted or scored, but not seriously weakened all 4 brake discs (1.1.14 (a) (ii))

Advice Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 2.0mm (5.2.3 (e))

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) Fail

Fail Offside Front Service brake excessively fluctuating (1.2.1 (e))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))

Fail Central Rear Seat belt buckle not functioning as intended (7.1.2 (d))

Fail Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



**Advice** 

**HV63ZKA** 

report date: 2024-03-29

MOT test number

507195260146

Result

Advice Nearside Rear Tyre worn close to legal limit/worn on edge nearing 2mm warning bars (5.2.3 (e))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Offside Rear Tyre worn close to legal limit/worn on edge nearing 2mm and stepped (5.2.3 (e))

MOT #8

MOT test number

962670373186

Result

✓ Passed

MOT #7

2020-03-04 13:41

MOT test number

678134228249

Result \( \sqrt{Passed} \)

Advice Nearside Front anti-roll bar end link has slight play in ball joint

Advice Front and rear brake discs becoming corroded

MOT #6 2019-02-14 09:26

MOT test number 918209658200

Result \rightarrow Passed

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**Advice** Both front tyres wearing on edges/worn close to legal limit.

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #5 2018-01-16 15:31

**MOT test number** 276217084382

MOT #4 2018-01-16 14:21

**MOT test number** 810330243390

**Result** X Failed

Fail Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc GAITER CLIP BROKEN (2.5.C.1a)

Advice Offside Rear Outer Tyre worn close to the legal limit TREAD GETTING LOW (4.1.E.1)

**Advice** Nearside Rear Outer Tyre worn close to the legal limit TREAD GETTING LOW (4.1.E.1)

MOT #3 2017-11-07 09:50

**MOT test number** 257383759535

**Result** ✓ Passed

MOT #2 2016-11-16 11:11

MOT test number 641272425403

**Result** 
✓ Passed

**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)

MOT #1 2016-11-16 11:11

MOT test number 588824589351

**Result** ★ Failed

**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)

**Pass with rectification** Nearside Stop lamp not working (1.2.1b)

CarCheck.co.uk page 6/13



#### Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	19 April 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

*		
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.		AULT
***************************************		
***************************************		
*************		
	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >


CarCheck.co.uk page 11/13



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-11-27
Last registration	2024-04-22
Complete history	See info



Registration #1	2013-11-27	9 mi
Registration #2	2016-11-16	23.087 mi
Registration #3	2016-11-16	23.087 mi
Registration #4	2017-11-07	31.834 mi
Registration #5	2018-01-16	32.377 mi
Registration #6	2018-01-16	32.377 mi
Registration #7	2019-02-14	52.710 mi
Registration #8		77.777 440
Registration #9		77.777 46
Registration #10		11.177 es
Registration #11		77.777 466
Registration #12		77.777 46
Registration #13		77.777 466

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 12/13



Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

## Safety ratings

NCAP rating	****
Video	see crash video



## Dimensions & weight

Width	1804 mm
Height	1507 mm
Length	4559 mm
Wheel base	2703 mm
Kerb weight	1302 kg
Max. allowed weight	1864 kg

# Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13