



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK 200 KOMPRESSOR
Colour	Silver
Year of manufacture	2005
Top speed	143 mph
0 - 60 mph	7.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	240 Nm at 3.000 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	209 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-02-02
Pictures	0
Listing price	View report

source: autoonline.co.uk



MOT history

MOT expiry date	2024-05-20
MOT pass rate	73 %
MOT passed	16
Failed MOT tests	6
Total advice items	39
Total items failed	14

MOT #22	2023-05-11 10:03
MOT test number	855783504843
Result	✓ Passed
Next expiry date	2024-05-20
Advice	Offside Front Tyre slightly damaged/cracking or perishing sidewall (5.2.3 (d) (ii))

MOT #21	2022-05-17 15:12
MOT test number	838968912224
Result	✓ Passed

MOT #20	2022-05-10 10:54
MOT test number	315589204407
Result	✗ Failed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Fail	Nearside Rear Subframe mounting prescribed area excessively corroded significantly reducing structural strength (5.3.6 (a) (i))

MOT #19	2021-05-21 13:40
MOT test number	318392262660
Result	✓ Passed

**MOT #18**

2021-05-10 16:09

MOT test number

849131628266

Result

✗ Failed

Fail Nearside Front Lower Suspension arm ball joint excessively worn centre lower (5.3.4 (a) (i))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Both front headlamp aims becoming hazy**Fail** Offside Front Suspension arm ball joint excessively worn centre lower (5.3.4 (a) (i))**Advice** Both front bottom arm front bushes worn ,,,front aluminium arms**MOT #17**

2020-11-19 08:27

MOT test number

577579579586

Result

✓ Passed

Advice Offside Track rod end ball joint has slight play (2.1.3 (b) (i))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Suspension rod ball joint has slight play (5.3.4 (a) (i))**MOT #16**

2020-11-18 15:56

MOT test number

920550454084

Result

✗ Failed

Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Suspension rod ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #15**

2019-06-06 13:38

MOT test number

665051828720

Result

✓ Passed

**MOT #14** 2019-05-31 13:48**MOT test number** 970680215307**Result** ✗ Failed

- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Brake pipe excessively corroded both front to rear (1.1.11 (c))
- Fail** Offside Rear Direction indicator incorrect colour (4.4.3 (a))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #13 2018-05-17 12:51**MOT test number** 388279062865**Result** ✓ Passed

- Advice** Brake pipe slightly corroded both front to rears (3.6.B.2c)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #12 2017-05-16 09:55**MOT test number** 348799849780**Result** ✓ Passed

- Advice** Central Items removed from driver's view prior to test
- Advice** Rear Direction indicator slightly discoloured both (1.4.A.2f)
- Advice** Engine cover and under tray fitted

**MOT #11** 2017-05-15 15:46**MOT test number** 135972826290**Result** ✗ Failed**Advice** Central Items removed from driver's view prior to test**Advice** Engine cover and under tray fitted**Fail** Horn not working (1.6.2a)**Advice** Rear Direction indicator slightly discoloured both (1.4.A.2f)**MOT #10** 2016-05-31 13:10**MOT test number** 440100719303**Result** ✓ Passed**Advice** Nearside hand brake weaker than offside**Advice** Under trays fitted**Advice** Direction indicator slightly discoloured both rear (1.4.A.2f)**MOT #9** 2015-06-16 16:06**MOT test number** 797407665171**Result** ✓ Passed**MOT #8** 2014-07-15 13:14**MOT test number** 627226294174**Result** ✓ Passed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2014-07-15 13:14**MOT test number** 545396794161**Result** ✗ Failed**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Centre Rear Stop lamp not working (1.2.1b)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)**MOT #6** 2013-07-18 09:39**MOT test number** 999129293115**Result** ✓ Passed**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front rear brake fluctuating, but not excessively (3.7.B.3)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #5** 2012-07-21 09:58**MOT test number** 976873502272**Result** ✓ Passed**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #4	2011-07-20 11:08
MOT test number	145201701216
Result	✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #3	2010-07-20 10:36
MOT test number	620231000222
Result	✓ Passed

MOT #2	2009-07-22 12:14
MOT test number	314373509201
Result	✓ Passed

MOT #1	2008-07-11 10:30
MOT test number	313513598176
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
20 May 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	20 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 YA05PBZ
Plate since	2019-06-29
Current registration	 YA05PBZ
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2005-07-22
Last registration	2023-05-11
Complete history	See info



Registration #1	2005-07-22	23 mi
Registration #2	2008-07-11	13.035 mi
Registration #3	2009-07-22	28.623 mi
Registration #4	2010-07-20	33.501 mi
Registration #5	2011-07-20	39.842 mi
Registration #6	2012-07-21	49.847 mi
Registration #7	2013-07-18	58.698 mi
Registration #8	2014-07-15	68.088 mi
Registration #9	2015-06-16	76.851 mi
Registration #10	2016-05-31	82.315 mi
Registration #11	2017-05-15	88.014 mi
Registration #12	2017-05-16	88.024 mi
Registration #13	2018-05-16	95.377 mi
Registration #14	2019-05-16	102.730 mi
Registration #15	2020-05-16	110.083 mi
Registration #16	2021-05-16	117.436 mi
Registration #17	2022-05-16	124.789 mi
Registration #18	2023-05-11	132.142 mi
Registration #19	2023-05-11	132.142 mi
Registration #20	2023-05-11	132.142 mi
Registration #21	2023-05-11	132.142 mi
Registration #22	2023-05-11	132.142 mi
Registration #23	2023-05-11	132.142 mi

More info >



Dimensions & weight

Width	1969 mm
Height	1296 mm
Length	4089 mm
Wheel base	2430 mm
Kerb weight	1390 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27194430552799