



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Black
Year of manufacture	2010
Top speed	122 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 3.250 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	57.6 mpg
Consumption combined	49.6 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-09-09
Pictures	14
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-17
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	47
Total items failed	13

MOT #20	2023-11-18 13:33
MOT test number	320238670607
Result	✓ Passed
Next expiry date	2024-11-17
Advice	Offside Front o/s/f seatbelt webbing starting to fray
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #19	2023-11-18 10:37
MOT test number	462573332841
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Offside Front o/s/f seatbelt webbing starting to fray
Fail	Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
Fail	Offside Front Road wheel fixing missing one wheel nut missing (5.2.1 (a) (i))

**MOT #18**

2022-10-28 15:26

**MOT test number**

565646218845

**Result**

✓ Passed

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2022-10-27 14:01

**MOT test number**

333598793996

**Result**

✗ Failed

- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #16**

2021-09-27 15:02

**MOT test number**

579504695400

**Result**

✓ Passed

- Advice** Seat belt buckle slightly damaged centre row central seat buckle and offside (7.1.2 (d))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**MOT #15**

2021-03-17 15:38

**MOT test number**

952280431547

**Result**

✓ Passed

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #14**

2021-03-16 11:07

**MOT test number**

331366795386

**Result**

✗ Failed

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge 215/60/HR16 (5.2.3 (e))

**Fail**

Offside Front Seat belt damaged (7.1.2 (b) (i))

**Minor**

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13**

2020-03-02 16:11

**MOT test number**

842290978049

**Result**

✓ Passed

**Advice**

Power steering close to minimum mark (2.1.5 (b) (i))

**Advice**

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**Advice**

Central Rear Child Seat fitted not allowing full inspection of adult belt

**Minor**

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Rear exhaust heat shield insecure

**Advice**

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice**

Brake fluid close to minimum mark (1.1.10 (d) (ii))

**MOT #12** 2020-03-02 14:23**MOT test number** 443266596184**Result** ✗ Failed

- Advice** Power steering close to minimum mark (2.1.5 (b) (i))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Rear exhaust heat shield insecure
- Advice** Brake fluid close to minimum mark (1.1.10 (d) (ii))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Central Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11** 2019-03-30 10:47**MOT test number** 849057395161**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2019-03-30 09:46**MOT test number** 341284487724**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Central Seat belt not functioning as intended MIDDLE (7.1.2 (c))

**MOT #9** 2018-03-27 09:20**MOT test number** 692601136848**Result** ✓ Passed

**MOT #8** 2018-03-27 09:20**MOT test number** 875758985372**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #7** 2017-03-28 09:23**MOT test number** 365147884286**Result** ✓ Passed**MOT #6** 2016-03-19 08:50**MOT test number** 890885390097**Result** ✓ Passed**Advice** Power steering fluid level low, but not below minimum (2.3.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2015-03-09 11:44**MOT test number** 195648365063**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)

**MOT #4** 2014-03-17 09:52**MOT test number** 449826774001**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-03-14 10:21**MOT test number** 196153974074**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2013-03-18 11:13**MOT test number** 775457173093**Result** ✓ Passed**MOT #1** 2013-03-18 11:13**MOT test number** 567697873022**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Offside Headlamp aim too high (1.8)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
17 November 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	17 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>HN10CHF</b>
Plate since	2019-03-28
Current registration	<b>HN10CHF</b>
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2010-03-30
Last registration	2023-11-18
Complete history	<a href="#">See info</a>



Registration #1	2010-03-30	9 mi
Registration #2	2013-03-18	32.411 mi
Registration #3	2014-03-14	44.249 mi
Registration #4	2014-03-17	44.249 mi
Registration #5	2015-03-09	55.233 mi
Registration #6	2016-03-19	65.614 mi
Registration #7	2017-03-28	79.205 mi
Registration #8	2018-03-27	89.619 mi
Registration #9	2018-03-27	89.619 mi
Registration #10	2019-03-30	103.313 mi
Registration #11	2019-03-30	103.313 mi
Registration #12	2019-03-30	103.313 mi
Registration #13	2019-03-30	103.313 mi
Registration #14	2019-03-30	103.313 mi
Registration #15	2019-03-30	103.313 mi
Registration #16	2019-03-30	103.313 mi
Registration #17	2019-03-30	103.313 mi
Registration #18	2019-03-30	103.313 mi
Registration #19	2019-03-30	103.313 mi
Registration #20	2019-03-30	103.313 mi
Registration #21	2019-03-30	103.313 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

**Engine number**

AU21080