



report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH HDI 900 ENTERPRISE P/V
Colour	Grey
Year of manufacture	2006
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	205 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-03-05
Pictures	4
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-01-21
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	57
Total items failed	12

MOT #20	2024-01-22 09:54
MOT test number	159653294961
Result	✓ Passed
Next expiry date	2025-01-21

MOT #19	2024-01-17 10:31
MOT test number	966913696283
Result	✗ Failed
<div><div>Fail</div>Offside Rear Outer Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))</div>	
<div><div>Minor</div>Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))</div>	
<div><div>Fail</div>Nearside Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced outer sill several places (6.1.1 (c) (i))</div>	
<div><div>Fail</div>Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))</div>	

MOT #18	2023-01-18 10:23
MOT test number	938443027042
Result	✓ Passed
<div><div>Advice</div>Brake pipe corroded, covered in grease or other material All pipes painted (1.1.11 (c))</div>	
<div><div>Advice</div>Brake pipe corroded, covered in grease or other material Two pipes at n/s/f corroded (1.1.11 (c))</div>	
<div><div>Minor</div>Nearside Front Brake pipe inadequately clipped or supported (1.1.11 (d) (i))</div>	

**MOT #17**

2022-01-19 12:13

MOT test number

131427336105

Result

✓ Passed

Advice

Nearside Rear Tyre slightly damaged Badly cracking & inner sidewall damaged. (5.2.3 (d) (ii))

Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated Small clip (6.1.7 (g) (i))

Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated Splitting (6.1.7 (g) (i))

MOT #16

2020-11-06 11:22

MOT test number

333747307870

Result

✓ Passed

Advice

Offside Front Outer cv boot clip missing

Advice

Nearside Front Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing cracks to inner sidewall (5.2.3 (d) (ii))

Advice

Trims fitted to all road wheels preventing full inspection of some components

Advice

Integral body structure is corroded but structural rigidity is not significantly reduced underside of vehicle (6.1.1 (c) (i))

Advice

Front Shock absorbers has slight external damage to the casing outer casings corroded, both sides (5.3.2 (b))



MOT #15

2019-06-26 07:46

MOT test number

946531370549

Result		✓ Passed
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice	Nearside Front wheel binding by hand	
Advice	Integral body structure is corroded but structural rigidity is not significantly reduced underside of vehicle (6.1.1 (c) (i))	
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))	
Advice	Trims fitted to all road wheels preventing full inspection of some components	
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))	
Advice	Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing cracks in tread (5.2.3 (d) (ii))	

**MOT #14**

2019-06-25 09:22

MOT test number

285164848785

Result**✗ Failed**

- Advice** Nearside Front wheel binding by hand
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Advice** Integral body structure is corroded but structural rigidity is not significantly reduced underside of vehicle (6.1.1 (c) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracks in tread (5.2.3 (d) (ii))
- Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Advice** Trims fitted to all road wheels preventing full inspection of some components
- Fail** Nearside Rear Brake pipe excessively corroded flexi to wheel cylinder (1.1.11 (c))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened inner face (1.1.14 (a) (ii))
- Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #13**

2018-06-15 11:08

MOT test number

306052073196

Result

✓ Passed

- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Slight play in strut top mount
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both discs on inner face (1.1.14 (a) (ii))
- Advice** Vehicle structure is corroded but structural rigidity is not significantly reduced Underside of vehicle (6.1.1 (c) (i))
- Advice** Offside Front Tyre has cracks in tread
- Advice** Trims fitted to all road wheels preventing full inspection of some components
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #12

2017-06-29 16:07

MOT test number

657593088678

Result

✓ Passed

- Advice** Vehicle structure has slight corrosion Covering most of the underside (6.1.A.1)
- Advice** Trims fitted to all road wheels
- Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

**MOT #11**

2017-06-24 10:33

MOT test number

513357762683

Result**✗ Failed****Advice** Hi level brake light not working**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Fail** Nearside Front coil spring broken (2.4.C.1a)**Advice** Spare tyre defective Serious cracks to visible sidewall**Advice** Trims fitted to all road wheels**Advice** Offside Front Suspension arm ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)**Advice** Vehicle structure has slight corrosion Covering most of the underside (6.1.A.1)**MOT #10**

2016-06-17 10:27

MOT test number

131150455726

Result**✓ Passed****Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner faces (3.5.1i)**Advice** 3rd brake light inop**Advice** Front Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)**MOT #9**

2015-06-30 17:43

MOT test number

559241085115

Result**✓ Passed****Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)

**MOT #8** 2015-06-29 12:53**MOT test number** 239880085441**Result** ✗ Failed**Fail** Offside Front brake disc in such a condition that it is seriously weakened (3.5.1i)**Advice** Power steering pipe(s) or hose(s) has slight seepage (2.3.3b)**Notice** Nail in offside rear tyre**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**MOT #7** 2014-05-22 14:04**MOT test number** 215822044125**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2014-05-22 14:04**MOT test number** 859702144198**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Rear Exhaust system not adequately supported (7.1.1)**MOT #5** 2013-05-29 12:57**MOT test number** 949889643178**Result** ✓ Passed**MOT #4** 2012-04-12 09:35**MOT test number** 467503302127**Result** ✓ Passed



MOT #3	2011-05-03 09:53
MOT test number	556053121189
Result	✓ Passed

MOT #2	2010-04-06 17:56
MOT test number	222776390035
Result	✓ Passed
<div>NoticeBoth rear tyres at 3mm.</div>	

MOT #1	2008-12-30 10:14
MOT test number	433885968389
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
21 January 2025

Tax status	Valid until 1 September
-------------------	-------------------------

Days left	125
------------------	-----

MOT expiry date	21 January 2025
------------------------	-----------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history


Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	YL55ECE
Plate since	2019-09-29
Current registration	YL55ECE
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-01-21
Last registration	2024-01-22
Complete history	See info



Registration #1	2006-01-21	26 mi
Registration #2	2008-12-30	13.439 mi
Registration #3	2010-04-06	16.486 mi
Registration #4	2011-05-03	16.985 mi
Registration #5	2012-04-12	17.931 mi
Registration #6	2013-05-29	18.916 mi
Registration #7	2014-05-22	19.690 mi
Registration #8	2015-06-29	20.494 mi
Registration #9	2015-06-30	20.494 mi
Registration #10	2016-06-17	21.835 mi
Registration #11	2017-06-24	22.065 mi
Registration #12	2018-06-29	22.277 mi
Registration #13	2019-06-29	22.277 mi
Registration #14	2020-06-29	22.277 mi
Registration #15	2021-06-29	22.277 mi
Registration #16	2022-06-29	22.277 mi
Registration #17	2023-06-29	22.277 mi
Registration #18	2024-01-22	22.277 mi
Registration #19	2024-01-22	22.277 mi
Registration #20	2024-01-22	22.277 mi
Registration #21	2024-01-22	22.277 mi

More info >



Dimensions & weight

Width	1600 mm
Kerb weight	1415 kg
Max. allowed weight	2315 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	DYUU3023783