






report date: 2024-03-29

General information

| Make | ТОҮОТА |
|---------------------|-------------------------------|
| Model | HILUX INVINCIBLE 4X4 D-4D DCB |
| Colour | Silver |
| Year of manufacture | 2011 |
| Top speed | 106 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 169 BHP |
|-------------------------|---------------------|
| Max. torque | 343 Nm at 3.400 rpm |
| Engine capacity | 2.982 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 29.7 mpg |
| Consumption extra urban | 42.2 mpg |
| Consumption combined | 36.7 mpg |



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-10-15


Pictures 32

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

| B 4 | \sim $-$ | | |
|-------|-------------|------|--------|
| 10.71 | $^{\prime}$ | hic | tory |
| 101 | C I | 1115 | I OI V |
| | • | | , |

| MOT expiry date | 2025-05-11 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 12 |
| Failed MOT tests | 3 |
| Total advice items | 18 |
| Total items failed | 2 |

| MOT #15 | 2024-04-22 09:26 |
|--------------------------------------|------------------|
| MOT test number | 265863290449 |
| Result | √ Passed |
| Next expiry date | 2025-05-11 |
| Advice Underside poor and very rusty | |

| MOT #14 | 2023-05-09 14:04 |
|---|---------------------|
| MOT test number | 581612819203 |
| Result | ✓ Passed |
| Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamp (4.7.1 (b) (i)) | os or light sources |
| Advice Underside poor and rusty | |

| MOT #13 | | 2022-04-28 10:44 |
|----------|---|------------------|
| MOT test | number | 322770519453 |
| Result | | ✓ Passed |
| | | |
| MOT #12 | | 2022-04-26 15:36 |
| MOT test | number | 426687128367 |
| Result | | X Failed |
| MAJOR | Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) | |

CarCheck.co.uk page 3/13



Result

YR61CXX report date: 2024-03-29

✓ Passed

MOT #11 2021-05-12 07:13
MOT test number 849215735718

MOT test number 649215755716

Advice Exhaust has a minor leak of exhaust gases Middle box (6.1.2 (a))

Advice Coil spring corroded Both fronts (5.3.1 (b) (i))

Advice Underbody and chassis corrosion

MOT #10 2021-03-16 13:51

MOT test number 434701650413

Result \rightarrow Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9 2020-05-13 12:43

MOT test number 321246926928

Result ✓ Passed

MOT #8 2019-05-21 15:30

MOT test number 188355618337

Result \rightarrow Passed

MOT #7 2018-05-22 11:12

MOT test number 739002813050

MOT #6 2017-04-19 10:56

MOT test number 313403779593

Result

Passed

CarCheck.co.uk page 4/13



report date: 2024-03-29

| MOT #5 | | 2016-04-22 08:16 |
|----------|---|------------------|
| MOT test | number | 363111604294 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Front Brake pad(s) wearing thin (3.5.1g) | |
| Advice | Nearside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Front Brake pad(s) wearing thin (3.5.1g) | |


| MOT #4 | 2015-04-07 11:40 |
|---|------------------|
| MOT test number | 298157695057 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2015-04-07 08:47 |
| MOT test number | 128767895061 |
| Result | X Failed |
| Fail Nearside Front coil spring broken (2.4.C.1a) | |

| MOT #2 | 2014-09-02 17:51 |
|---|------------------|
| MOT test number | 396685144273 |
| Result | ✓ Passed |
| Advice Tyre worn close to the legal limit (4.1.E.1) | |
| Notice Damage to n/s/f bumper | |

CarCheck.co.uk page 5/13



report date: 2024-03-29



CarCheck.co.uk page 6/13



Tax & MOT check



Days left 187

MOT expiry date 11 May 2025

Full MOT history See MOT history

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

| _ | |
|--------|----------|
| Owner | hictory |
| OWITEI | HIISLULY |

| * | | |
|---|-----------|-----|
| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full | | DTA |
| *************************************** | | |
| | | |
| | | |
| | | |
| | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this TOYOTA had different number plates. | | |
| Number of plates | | |
| Current registration | UK W | |
| Plate since | | |
| Current registration | NK NA | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info >

CarCheck.co.uk page 11/13



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2011-09-20 |
| Last registration | 2024-04-22 |
| Complete history | See info |



| Registration #1 | 2011-09-20 | 28 mi |
|------------------|------------|------------|
| Registration #2 | 2014-09-02 | 73.093 mi |
| Registration #3 | 2014-09-02 | 73.093 mi |
| Registration #4 | 2015-04-07 | 76.037 mi |
| Registration #5 | 2015-04-07 | 76.037 mi |
| Registration #6 | 2016-04-22 | 84.642 mi |
| Registration #7 | 2017-04-19 | 93.201 mi |
| Registration #8 | 2018-05-22 | 103.594 mi |
| Registration #9 | 2019-05-21 | 109.571 mi |
| Registration #10 | | 71.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 71.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 71.777 es |
| Registration #15 | | 11.777 es |
| Registration #16 | | 11.777 es |
| Registration #17 | | 9.70 es |

More info >

CarCheck.co.uk page 12/13



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Dimensions & weight

| Width | 1835 mm |
|---------------------|---------|
| Height | 1860 mm |
| Length | 5260 mm |
| Kerb weight | 1975 kg |
| Max. allowed weight | 3080 kg |

Additional information

| Fuel delivery | Direct Injection |
|-----------------|------------------|
| Number of doors | 4 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 1KD5220094 |

CarCheck.co.uk page 13/13