



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS TDI
Colour	Black
Year of manufacture	2008
Top speed	127 mph
0 - 60 mph	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	24.8 mpg
Consumption extra urban	42.8 mpg
Consumption combined	33.6 mpg
CO2 emission	152 g/km
CO2 label	G






Internet history

Entry 1

Date	2022-02-06
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-13
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	18
Total items failed	3

MOT #15	2024-02-14 18:42
MOT test number	379515144030
Result	✓ Passed
Next expiry date	2025-02-13

MOT #14	2023-04-13 15:55
MOT test number	632377622116
Result	✓ Passed

MOT #13	2023-03-30 15:20
MOT test number	159295250055
Result	✗ Failed

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Front Oil leak, but not excessive (8.4.1 (a) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #12	2022-06-15 09:29
MOT test number	643570900408
Result	✓ Passed

**MOT #11**

2021-07-07 15:06

MOT test number

832907444940

Result

✓ Passed

Advice

Front Exhaust mounting defective (6.1.2 (a))

Advice

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #10

2021-07-06 08:48

MOT test number

115271547915

Result

✗ Failed

Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Fail

Nearside Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice

Front Exhaust mounting defective (6.1.2 (a))

Advice

Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))

MOT #9

2020-07-01 08:28

MOT test number

933675094464

Result

✓ Passed

Minor

Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #8** 2019-07-15 13:03**MOT test number** 131075818732**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #7** 2018-07-26 13:58**MOT test number** 689100763200**Result** ✓ Passed**MOT #6** 2016-04-01 10:50**MOT test number** 588603758781**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2016-04-01 10:40**MOT test number** 577390295140**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)



MOT #4	2015-04-07 16:27
MOT test number	576987295015
Result	✓ Passed
Advice	Nearside Front Anti-roll bar has slight play in a ball joint (2.4.G.2)
Advice	Offside Front Lower Anti-roll bar has slight play in a ball joint (2.4.G.2)

MOT #3	2013-11-20 12:02
MOT test number	315064023369
Result	✓ Passed

MOT #2	2012-11-15 09:08
MOT test number	585750022381
Result	✓ Passed

MOT #1	2011-12-02 12:54
MOT test number	247426631306
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
30 March 2024

✓

MOT

Expires:
13 February 2025

Tax status	Expired at 30 March 2024
Days left	29 days too late
MOT expiry date	13 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 KP58SDO
Plate since	2019-06-29
Current registration	 KP58SDO
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-11-18
Last registration	2024-02-14
Complete history	See info



Registration #1	2008-11-18	6 mi
Registration #2	2011-12-02	16.559 mi
Registration #3	2012-11-15	25.739 mi
Registration #4	2013-11-20	36.207 mi
Registration #5	2015-04-07	52.454 mi
Registration #6	2016-04-01	59.589 mi
Registration #7	2016-04-01	59.589 mi
Registration #8	2018-07-26	62.448 mi
Registration #9	2019-07-15	65.754 mi
Registration #10	2020-05-20	66.277 mi
Registration #11	2020-05-20	66.277 mi
Registration #12	2020-05-20	66.277 mi
Registration #13	2020-05-20	66.277 mi
Registration #14	2020-05-20	66.277 mi
Registration #15	2020-05-20	66.277 mi
Registration #16	2020-05-20	66.277 mi
Registration #17	2020-05-20	66.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1552 kg
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CBA 098124