





report date: 2024-03-29

General information

Make	SUZUKI
Model	JIMNY SZ4
Colour	Black
Year of manufacture	2014
Top speed	84 mph
0 - 60 mph	17.2 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	85 BHP
Max. torque	110 Nm at 4.100 rpm
Engine capacity	1.328 сс
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.7 mpg
CO2 emission	167 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

_		•		_	-
-	n	т	rv	,	

Elitiy 1	
Date	2021-06-05
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history	ΜO	Γh	nist	orv	
-------------	----	----	------	-----	--

MOT expiry date	2024-11-05
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	6
Total items failed	2

MOT #9	2023-10-25 08:52
MOT test number	222673892997
Result	✓ Passed
Next expiry date	2024-11-05

MOT #8	2022-10-28 15:05
MOT test number	253696117943
Result	✓ Passed

MOT #7	2022-10-28 10:02
--------	------------------

MOT test number 444298525472

Result X Failed

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

 MOT #6
 2021-11-06 14:34

 MOT test number
 504721469758

 Result
 ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened Both sides. (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #5

MOT test number

Result

Advice

Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #4

MOT test number

Result

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

 MOT #3
 2018-12-04 12:40

 MOT test number
 179237430820

 Result
 ✓ Passed

MOT #2

MOT test number

909455967866

Result

✓ Passed

 MOT #1
 2017-11-23 10:06

 MOT test number
 408565303565

 Result
 X Failed

Fail Service brake: efficiency below requirements (3.7.B.7)

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	5 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.	

	More info >
Plate changes	
See in this check if this SUZUKI had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-12-17
Last registration	2023-10-25
Complete history	See info



Registration #1	2014-12-17	22 mi
Registration #2	2017-11-23	10.371 mi
Registration #3	2017-11-23	10.731 mi
Registration #4	2018-12-04	12.640 mi
Registration #5	2019-11-19	15.103 mi
Registration #6	2020-11-17	19.536 mi
Registration #7		11.777 es
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es

More info >

CarCheck.co.uk page 10/11



GX64EHG report date: 2024-03-29

<u> </u>		_	
Dimer	ncinne	・人・ハ	MAIGHT
	כווטוכו	CX 1	WCIGIIL

Width	1600 mm
Height	1705 mm
Length	3695 mm
Wheel base	2250 mm
Kerb weight	1150 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	M13A-2358546

CarCheck.co.uk page 11/11