



**NXI2SYG**


report date: 2024-03-29

General information

Make	SUZUKI
Model	SWIFT SZ3
Colour	Black
Year of manufacture	2012
Top speed	103 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	93 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	116 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-05-22
Pictures	11
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-10
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	29
Total items failed	10

MOT #13	2024-02-06 11:07
MOT test number	344121743041
Result	✓ Passed
Next expiry date	2025-02-10
Advice	Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Offside Front Tyre slightly damaged/cracking or perishing slightly cracking in tread (5.2.3 (d) (ii))
Advice	Offside Front Brake pipe corroded, covered in grease or other material slightly corroded (1.1.11 (c))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #12**

2024-02-03 08:38

**MOT test number**

715941292275

**Result**

✗ Failed

**Advice** Offside Front Tyre slightly damaged/cracking or perishing slightly cracking in tread (5.2.3 (d) (ii))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Brake pipe corroded, covered in grease or other material slightly corroded (1.1.11 (c))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**MOT #11**

2023-02-08 14:43

**MOT test number**

116686259576

**Result**

✓ Passed

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10**

2022-02-11 14:22

**MOT test number**

745271076906

**Result**

✓ Passed

**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #9**

2022-02-10 07:45

**MOT test number**

631202848121

**Result****✗ Failed**

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))
- Fail** Brake pipe excessively corroded both sides rear (1.1.11 (c))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))

**MOT #8**

2021-02-27 10:23

**MOT test number**

780898816414

**Result****✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #7**

2020-03-14 08:37

**MOT test number**

877596226028

**Result****✓ Passed**

- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #6** 2019-03-16 13:43**MOT test number** 265364922047**Result** ✓ Passed**MOT #5** 2018-02-28 10:34**MOT test number** 808582810503**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2018-02-28 10:34**MOT test number** 296061903776**Result** ✗ Failed**Pass with rectification** Nearside Front Valve stem seriously damaged (4.1.D.1e)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Front Valve stem seriously damaged (4.1.D.1e)**MOT #3** 2017-02-25 10:52**MOT test number** 525049045998**Result** ✓ Passed**MOT #2** 2016-03-04 13:19**MOT test number** 196013572257**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)



MOT #12015-02-19 17:27

MOT test number949830555046

Result✓ Passed

**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

**Notice** Both rear tyres cracking

**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
10 February 2025

Tax status	Valid until 1 July
Days left	62
MOT expiry date	10 February 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-





Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	<b>XX12SYG</b>
Plate since	2024-03-29
Current registration	<b>XX12SYG</b>
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-08
Last registration	2024-02-06
Complete history	<a href="#">See info</a>



Registration #1	2012-03-08	20 mi
Registration #2	2015-02-19	47.319 mi
Registration #3	2016-03-04	63.766 mi
Registration #4	2017-02-25	70.167 mi
Registration #5	2018-02-28	78.485 mi
Registration #6	2018-02-28	78.485 mi
Registration #7	2019-03-16	86.062 mi
Registration #8	2020-03-14	95.379 mi
Registration #9	2020-03-14	95.379 mi
Registration #10	2020-03-14	95.379 mi
Registration #11	2020-03-14	95.379 mi
Registration #12	2020-03-14	95.379 mi
Registration #13	2020-03-14	95.379 mi
Registration #14	2020-03-14	95.379 mi
Registration #15	2020-03-14	95.379 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	94%
Children	82%
Pedestrian	62%
Safety systems	71%
Overall rating	83%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1695 mm
Height	1510 mm
Length	3850 mm
Wheel base	2430 mm
Kerb weight	1050 kg
Max. allowed weight	1480 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Engine number	K12B-1407482