





### General information

Make	VAUXHALL
Model	AGILA DESIGN
Colour	Green
Year of manufacture	2010
Top speed	109 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption


Power	85 BHP
Max. torque	114 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	60.1 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D







Internet history	
Entry 1	
Date	2021-07-20
Pictures	2
Listing price	View report



source: autotrader.co.uk



# MOT history

MOT expiry date	2024-04-07
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	6
Total items failed	4

MOT #13	2023-03-25 10:31
MOT test number	650109860881
Result	✓ Passed
Next expiry date	2024-04-07
Advice Offside Front Coil spring corroded (5.3.1 (b) (i))	

MOT #12	2022-04-08 14:19
MOT test number	537287224130
Result	✓ Passed

MOT #11		2021-03-03 09:04
MOT test	number	219916538266
Result		✓ Passed
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive n	novement (5.3.4 (a)
Advice	Offside Front cv joint worn but not excesive	
<b>Advice</b> (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive	e movement (5.3.4

MOT #10	2020-02-27 15:41
MOT test number	572366264281
Result	✓ Passed



YR10KG0 report date: 2024-03-29

MOT #9	<b>9</b> 2020-	-02-27 13:53
MOT te	est number 76	1506435979
Result		🗙 Failed
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	

MOT #8	2019-02-26 13:05
MOT test number	968898870409
Result	✓ Passed

MOT #7		2018-02-26 09:04
MOT test	number	423347058949
Result		✓ Passed
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #6	2017-02-13 10:52
MOT test number	221304777968
Result	✓ Passed
MOT #5	2016-02-22 12:27

MOT test number	728316310195
Result	✓ Passed

MOT #4	2015-02-25 10:01
MOT test number	145566355091
Result	✓ Passed





MOT #3		2014-03-03 16:08
MOT test number		966832964096
Result		✓ Passed
MOT #2		2014-03-03 16:08
MOT test number		388032064006
Result		🗙 Failed
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)	
Pass with rectification	Offside Windscreen wiper blade missing (8.2.2)	

MOT #1	2013-03-18 13:39
MOT test number	328097473027
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 April 2025	<b>X</b> <b>MOT</b> Expired: 7 April 2024
Tax status	Valid until 1 April 338
Days left MOT expiry date	7 April 2024
Full MOT history	See MOT history

# Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





#### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

#### Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200





### Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
ACCOUNTS AND A DESCRIPTION OF A DESCRIPR	
And and a second s	
**********	
********	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-04-08
Last registration	2023-03-25
Complete history	See info



Registration #1	2010-04-08	24 mi
Registration #2	2013-03-18	13.475 mi
Registration #3	2014-03-03	13.790 mi
Registration #4	2015-02-25	22.109 mi
Registration #5	2016-02-22	25.585 mi
Registration #6	2017-02-13	31.027 mi
Registration #7	2018-02-26	38.755 mi
Registration #8		11.117 esi
Registration #9		11.777 esi
Registration #9 Registration #10		00.000 est
-		01,000 est 01,000 est 01,000 est
Registration #10		01,000 est 01,000 est 01,000 est 01,000 est
Registration #10 Registration #11		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est



YR10KG0 report date: 2024-03-29

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Max. allowed weight	1485 kg
Additional information	
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2