



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 DRIVE SE START/STOP
Colour	Blue
Year of manufacture	2011
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-08-26
Pictures	1
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-09-07
MOT pass rate	55 %
MOT passed	11
Failed MOT tests	9
Total advice items	27
Total items failed	14

## MOT #20 2023-09-08 14:15

MOT test number 159842300239

Result ✓ Passed

Next expiry date 2024-09-07

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
rearmost bush (5.3.4 (a) (i))

**Advice** Offside headlight slightly loose

## MOT #19 2023-09-01 08:08

MOT test number 596077812658

Result ✗ Failed

**MAJOR** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MAJOR** Nearside Headlamp light intensity severely reduced (4.1.4 (a))

**Advice** Offside headlight slightly loose

**MAJOR** Offside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

**MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement  
rearmost bush (5.3.4 (a) (i))

## MOT #18 2022-08-17 11:38

MOT test number 814748335195

Result ✓ Passed

**MOT #17** 2021-09-02 15:17**MOT test number** 431353124794**Result** ✓ Passed**MOT #16** 2021-09-02 15:17**MOT test number** 337898833013**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #15** 2021-03-08 09:53**MOT test number** 977951257123**Result** ✓ Passed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Both rear tyres wearing out of shape**MOT #14** 2021-03-08 09:53**MOT test number** 471394394309**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Both rear tyres wearing out of shape**MOT #13** 2020-03-02 09:30**MOT test number** 369153371123**Result** ✓ Passed

**MOT #12** 2019-03-11 08:30**MOT test number** 165532402987**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Both rear tyres worn out of shape slightly**MOT #11** 2019-03-11 08:30**MOT test number** 778932349671**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Both rear tyres worn out of shape slightly**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2018-03-06 16:05**MOT test number** 593004261190**Result** ✓ Passed**MOT #9** 2018-02-24 12:14**MOT test number** 445598696677**Result** ✗ Failed**Fail** Brake pedal anti-slip provision missing (3.3.A.1b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Inner Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)



MOT #8 2017-02-27 13:13

MOT test number 413150579380

Result ✓ Passed

MOT #7 2017-02-27 13:13

MOT test number 364438567772

Result ✗ Failed

**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)

**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)

MOT #6 2016-02-11 11:43

MOT test number 527722025631

Result ✓ Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2016-02-11 10:51**MOT test number** 984036752187**Result** ✗ Failed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #4** 2015-01-27 12:40**MOT test number** 458937625003**Result** ✓ Passed**MOT #3** 2015-01-27 12:40**MOT test number** 498927825022**Result** ✗ Failed

- Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)

**MOT #2** 2014-01-08 13:07**MOT test number** 678918104080**Result** ✓ Passed**MOT #1** 2014-01-08 10:39**MOT test number** 687628604047**Result** ✗ Failed

- Fail** Nearside Rear Rear position lamp(s) incorrect colour (1.1.A.3e)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
7 September 2024

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	124
<b>MOT expiry date</b>	7 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	A
<b>Single payment (12 months)</b>	£ 0,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	Not applicable





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2011-01-08
Last registration	2023-09-08
Complete history	<a href="#">See info</a>



Registration #1	2011-01-08	19 mi
Registration #2	2014-01-08	25.905 mi
Registration #3	2014-01-08	25.905 mi
Registration #4	2015-01-27	32.105 mi
Registration #5	2016-02-11	43.635 mi
Registration #6	2016-02-11	43.635 mi
Registration #7	2017-02-27	56.762 mi
Registration #8	2017-02-27	56.762 mi
Registration #9	2018-02-24	71.442 mi
Registration #10	2018-03-06	71.535 mi
Registration #11	2019-03-11	85.724 mi
Registration #12	2019-03-11	85.724 mi
Registration #13	2019-03-11	85.724 mi
Registration #14	2019-03-11	85.724 mi
Registration #15	2019-03-11	85.724 mi
Registration #16	2019-03-11	85.724 mi
Registration #17	2019-03-11	85.724 mi
Registration #18	2019-03-11	85.724 mi
Registration #19	2019-03-11	85.724 mi
Registration #20	2019-03-11	85.724 mi
Registration #21	2019-03-11	85.724 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1369 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	1408539