



report date: 2024-03-29

General information

Make	FORD
Model	KA ZETEC
Colour	Silver
Year of manufacture	2009
Top speed	99 mph
0 - 60 mph	13.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	44.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-11
Pictures	24
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-02
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	26
Total items failed	3

MOT #15	2024-02-19 09:47
---------	------------------

MOT test number	923836266458
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-03-02
------------------	------------

- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear exhaust box corroded
- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #14**

2023-02-28 13:36

**MOT test number**

634279778425

**Result**

✓ Passed

**Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Exhaust rear box corroding**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Front Outer Road wheel slightly distorted (5.2.2 (c) (i))**MOT #13**

2023-02-28 13:36

**MOT test number**

236438353395

**Result**

✗ Failed

**Advice** Nearside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Outer Road wheel slightly distorted (5.2.2 (c) (i))**Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Advice** Offside Rear Lower Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Exhaust rear box corroding

**MOT #12** 2022-03-03 14:08**MOT test number** 596613491815**Result** ✓ Passed**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear exhaust corroded**Advice** Rear Suspension component corroded but not seriously weakened axle beam (5.3.3 (b) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Service brake binding but not excessively (1.2.1 (f))**MOT #11** 2020-12-10 13:03**MOT test number** 943991596441**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-12-13 12:52**MOT test number** 220492850154**Result** ✓ Passed**MOT #9** 2018-12-12 12:58**MOT test number** 466475216579**Result** ✓ Passed**MOT #8** 2017-11-28 11:16**MOT test number** 997659198054**Result** ✓ Passed**MOT #7** 2016-11-16 15:51**MOT test number** 583642414748**Result** ✓ Passed

**MOT #6** 2016-11-16 11:54**MOT test number** 488819916910**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #5** 2015-11-30 17:10**MOT test number** 190004491671**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #4** 2014-09-09 11:56**MOT test number** 658512254231**Result** ✓ Passed**MOT #3** 2014-09-09 11:56**MOT test number** 336582454428**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2013-09-13 17:22**MOT test number** 529416653201**Result** ✓ Passed**MOT #1** 2012-04-17 17:45**MOT test number** 767198302106**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
2 March 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	2 March 2025
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-09-29
Current registration	XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-01
Last registration	2024-02-19
Complete history	<a href="#">See info</a>



Registration #1	2009-10-01	15 mi
Registration #2	2012-04-17	6.986 mi
Registration #3	2013-09-13	14.418 mi
Registration #4	2014-09-09	20.560 mi
Registration #5	2015-11-30	26.601 mi
Registration #6	2016-11-16	29.541 mi
Registration #7	2016-11-16	29.543 mi
Registration #8	2017-11-28	32.145 mi
Registration #9	2019-05-29	35.377 mi
Registration #10	2019-05-29	35.377 mi
Registration #11	2019-05-29	35.377 mi
Registration #12	2019-05-29	35.377 mi
Registration #13	2019-05-29	35.377 mi
Registration #14	2019-05-29	35.377 mi
Registration #15	2019-05-29	35.377 mi
Registration #16	2019-05-29	35.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1702 mm
Height	1505 mm
Length	3620 mm
Wheel base	2300 mm
Kerb weight	940 kg
Max. allowed weight	1320 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	5187434