



report date: 2024-03-29

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Blue
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-26
Pictures	7
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-05-31
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	23
Total items failed	3

MOT #13 2023-06-01 10:56

MOT test number 488382396429

Result ✓ Passed

Next expiry date 2024-05-31

- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge edge and perishing (5.2.3 (e))
- Advice** Rear Coil spring corroded both (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened and rear (1.1.14 (a) (ii))
- Advice** Front Service brake fluctuating, but not excessively and rear (1.2.1 (e))
- Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing edge (5.2.3 (d) (ii))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Oil leak, but not excessive (8.4.1 (a) (i))
- Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #12 2022-04-04 08:38

MOT test number 436852159140

Result ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2021-03-25 14:55**MOT test number** 384445401036**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #10** 2021-03-25 11:13**MOT test number** 691545099811**Result** ✗ Failed**Fail** Offside Brake pipe excessively corroded front to rear (1.1.11 (c))**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Offside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #9** 2020-03-24 09:32**MOT test number** 683550887479**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**MOT #8** 2019-03-26 11:38**MOT test number** 441145893610**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))



MOT #7	2018-03-12 16:08
---------------	------------------

MOT test number	210183391402
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2017-04-03 13:42
---------------	------------------

MOT test number	135211631267
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Brake pipe slightly corroded to rear (3.6.B.2c)
---------------	---

Advice	Offside Front Brake pipe slightly corroded (3.6.B.2c)
---------------	---

Advice	Nearside Front Brake pipe slightly corroded to rear (3.6.B.2c)
---------------	--

Advice	Nearside Front Brake pipe slightly corroded (3.6.B.2c)
---------------	--

MOT #5	2015-10-01 09:33
---------------	------------------

MOT test number	467360729246
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-09-24 11:26
---------------	------------------

MOT test number	197217364202
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2013-09-24 12:07
---------------	------------------

MOT test number	295307963215
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2012-09-24 11:16
---------------	------------------

MOT test number	329148262272
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #1	2011-09-26 10:55
MOT test number	819689261200
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
31 May 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	31 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-06-29
Previous owner since	2019-06-29
Number of owners	1
Current owner since	2019-06-29
Previous owner since	2019-06-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 YH58NBY
Plate since	2019-06-29
Current registration	 YH58NBY
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-09-29
Last registration	2023-06-01
Complete history	See info



Registration #1	2008-09-29	17 mi
Registration #2	2011-09-26	9.088 mi
Registration #3	2012-09-24	11.786 mi
Registration #4	2013-09-24	14.283 mi
Registration #5	2014-09-24	17.664 mi
Registration #6	2015-10-01	22.563 mi
Registration #7	2017-04-03	29.384 mi
Registration #8	2018-03-12	45.146 mi
Registration #9	2019-03-29	55.277 mi
Registration #10	2020-03-29	65.277 mi
Registration #11	2021-03-29	75.277 mi
Registration #12	2022-03-29	85.277 mi
Registration #13	2023-03-29	95.277 mi
Registration #14	2024-03-29	105.277 mi
Registration #15	2025-03-29	115.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564