



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D S
Colour	Blue
Year of manufacture	2005
Top speed	130 mph
0 - 60 mph	8.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	62.8 mpg
Consumption combined	50.4 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-26
Pictures	48
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-13
MOT pass rate	65 %
MOT passed	17
Failed MOT tests	9
Total advice items	68
Total items failed	21

MOT #26 2024-03-14 17:08

MOT test number 348591796576

Result ✓ Passed

Next expiry date 2025-03-13

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #25 2024-03-12 14:32

MOT test number 466687973721

Result ✗ Failed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Shock absorbers has negligible damping effect (5.3.2 (d))
- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**MOT #24** 2023-03-08 15:36**MOT test number** 700752601455**Result** ✓ Passed**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**MOT #23** 2022-02-15 11:06**MOT test number** 263353596093**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Brake disc worn, but not excessively both rear (1.1.14 (a) (i))**MOT #22** 2021-02-12 16:06**MOT test number** 591786865513**Result** ✓ Passed**MOT #21** 2021-02-10 10:06**MOT test number** 415891892737**Result** ✗ Failed**Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #20** 2020-01-28 17:06**MOT test number** 993557893505**Result** ✓ Passed

**MOT #19**

2020-01-28 15:35

MOT test number

197695812589

Result**✗ Failed****Advice** Exhaust mounting defective rear mount (6.1.2 (a))**Fail** Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #18**

2018-10-04 14:07

MOT test number

208854911613

Result**✓ Passed****Advice** Engine cover fitted**Advice** Rear exhaust bracket broken away from tail pipe system still secure**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Under tray fitted**MOT #17**

2018-10-04 11:02

MOT test number

621445118310

Result**✗ Failed****Advice** Under tray fitted**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Fail** Nearside Rear Parking brake inoperative on one side (1.4.1 (a))**Advice** Engine cover fitted**Advice** Rear exhaust bracket broken away from tail pipe system still secure**Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))

**MOT #16**

2017-09-21 15:04

MOT test number

913567863220

Result

✓ Passed

Advice Slight play in both rear anti roll bar link pin balljoints**Advice** 1 x rear exhaust mounting bracket broken**Advice** Rear shock absorber bump stops worn**Advice** 1 x rear exhaust mounting bracket corroded**MOT #15**

2017-09-20 08:59

MOT test number

195607906179

Result

✗ Failed

Advice Slight play in both rear anti roll bar link pin balljoints**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** 1 x rear exhaust mounting bracket broken**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Rear shock absorber bump stops worn**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** 1 x rear exhaust mounting bracket corroded**MOT #14**

2016-09-07 10:53

MOT test number

366555654199

Result

✓ Passed

Advice Corrosion to exhaust**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Both front tyres worn on edges

**MOT #13** 2015-09-09 13:11**MOT test number** 643845715292**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Corrosion to exhaust**MOT #12** 2014-09-25 10:53**MOT test number** 809958764280**Result** ✓ Passed**MOT #11** 2014-09-24 12:35**MOT test number** 145787764270**Result** ✗ Failed**Fail** Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Offside Front Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Notice** (advise) rear exhaust heat shield hanging down insecure**MOT #10** 2014-02-27 15:09**MOT test number** 608688054032**Result** ✓ Passed**Advice** Nearside Front Radius arm has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Front Radius arm has slight play in a pin/bush (2.4.G.2)**Advice** Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**MOT #9**

2014-02-27 13:11

MOT test number

677988554054

Result**✗ Failed**

- Advice** Nearside Front Radius arm has slight play in a pin/bush (2.4.G.2)
- Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Advice** Offside Front Radius arm has slight play in a pin/bush (2.4.G.2)
- Advice** Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #8

2013-03-11 16:37

MOT test number

217510873044

Result**✓ Passed**

- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Both outer tail lamps inoperative
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Windscreen in poor condition
- Advice** Nearside Rear Shock absorber has slight external damage to the casing (2.7.2a)

**MOT #7**

2013-03-11 12:01

MOT test number

506570973088

Result**✗ Failed**

- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Windscreen in poor condition
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Both outer tail lamps inoperative
- Advice** Nearside Rear Shock absorber has slight external damage to the casing (2.7.2a)
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #6

2012-03-13 13:49

MOT test number

189963272438

Result**✓ Passed**

- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Notice** Under-trays fitted obscuring some underside components
- Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2011-02-28 13:20**MOT test number** 109869851069**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Windscreen in poor condition - chipped and scratched**MOT #4** 2010-03-01 10:57**MOT test number** 132310460406**Result** ✓ Passed**Advice** Nearside Front front brake juddering slightly (3.7.A.2b)**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2009-03-03 15:56**MOT test number** 164822169010**Result** ✓ Passed**MOT #2** 2009-03-03 12:18**MOT test number** 181032769465**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2008-02-12 11:28**MOT test number** 622393448054**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
13 March 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	13 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	28
First mileage registration	2005-03-07
Last registration	2024-03-14
Complete history	See info



Registration #1	2005-03-07	28 mi
Registration #2	2008-02-12	33.844 mi
Registration #3	2009-03-03	45.231 mi
Registration #4	2009-03-03	45.231 mi
Registration #5	2010-03-01	54.134 mi
Registration #6	2011-02-28	67.566 mi
Registration #7	2012-03-13	76.415 mi
Registration #8	2013-03-11	86.840 mi
Registration #9	2013-03-11	86.840 mi
Registration #10	2014-02-27	99.135 mi
Registration #11	2014-02-27	99.135 mi
Registration #12	2014-09-24	106.943 mi
Registration #13	2014-09-25	106.943 mi
Registration #14	2015-09-09	115.178 mi
Registration #15	2015-09-09	115.178 mi
Registration #16	2015-09-09	115.178 mi
Registration #17	2015-09-09	115.178 mi
Registration #18	2015-09-09	115.178 mi
Registration #19	2015-09-09	115.178 mi
Registration #20	2015-09-09	115.178 mi
Registration #21	2015-09-09	115.178 mi
Registration #22	2015-09-09	115.178 mi
Registration #23	2015-09-09	115.178 mi
Registration #24	2015-09-09	115.178 mi
Registration #25	2015-09-09	115.178 mi
Registration #26	2015-09-09	115.178 mi

Registration #27	2025-05-20	25,000,000
Registration #28	2025-05-20	25,000,000

[More info >](#)



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1452 mm
Length	4468 mm
Wheel base	2640 mm
Kerb weight	1457 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	4003597