





report date: 2024-03-29

General information

Make	BMW
Model	X1 SDRIVE18D SE
Colour	Blue
Year of manufacture	2017
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	330 Nm at 1.750 rpm
Engine capacity	1.995 сс
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	76.4 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-01-29

Pictures 6

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

	~-				
10/1/	TC	h		-	r\ /
1011		ш	51	LUI	l V
	•			-	. ,

MOT expiry date	2024-08-19
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	8
Total items failed	0

MOT #6	2023-08-16 13:40
MOT test number	805613703267
Result	✓ Passed
Next expiry date	2024-08-19

MOT #5	2023-08-14 15:21
MOT test number	902773355498
Result	× Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm 225/45/ZR17 101W X/L (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 225/45/ZR17 101W X/L (5.2.3 (e))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm 225/45/ZR17 101W X/L (5.2.3 (e))

MOT #4	2022-08-17 11:15
MOT test number	472045694542
Result	✓ Passed
MOT #3	2021-08-20 08:56
MOT test number	928371205223

Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2020-09-02 15:50

MOT test number 414080061950

Result ✓ Passed

Advice

Nearside Rear Tyre slightly damaged/cracking or perishing treads perished with small cuts (5.2.3

(d) (ii))

MOT #1 2020-09-01 13:54

MOT test number 770268379953

Result X Failed

MAJOR Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing treads perished with small cuts (5.2.3 (d) (ii))

MAJOR Offside Rear Outer Position lamp lens seriously defective (4.2.1 (b))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	19 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



faste since

RK670DE

report date: 2024-03-29

More info >

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this BMW had different number plates.

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-28
Last registration	2023-08-16
Complete history	See info



Registration #1	2017-09-28	8 mi
Registration #2	2020-09-01	38.218 mi
Registration #3	2020-09-02	38.219 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1821 mm
Height	1598 mm
Length	4439 mm
Wheel base	2670 mm
Kerb weight	1430 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	51 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/

Number of axles 2

Engine number 76629901