



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 T5 SE LUX PREMIUM
Colour	Blue
Year of manufacture	2009
Top speed	150 mph
0 - 60 mph	7.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	230 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	21.9 mpg
Consumption extra urban	42.8 mpg
Consumption combined	31.7 mpg
CO2 emission	209 g/km
CO2 label	K





Internet history

Entry 2

Date 2021-09-25

Pictures 7

Listing price [View report](#)



source: yesauto.com

Entry 1

Date 2021-09-24

Pictures 12

Listing price [View report](#)



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-07
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	54
Total items failed	1

MOT #15	2023-11-06 12:46
MOT test number	511039968974
Result	✓ Passed
Next expiry date	2024-11-07
Advice	Offside Rear All direction indicators slightly discoloured (4.4.3 (a))
Advice	Nearside Rear All direction indicators slightly discoloured (4.4.3 (a))
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #14	2022-11-08 08:43
MOT test number	141613260457
Result	✓ Passed
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))

**MOT #13**

2022-11-07 10:37

MOT test number

882637285874

Result**✗ Failed**

- Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))
- MAJOR** Offside Front Outline marker lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12

2021-11-08 13:09

MOT test number

682364434420

Result**✓ Passed****MOT #11**

2020-09-28 09:12

MOT test number

185208110057

Result**✓ Passed**

- Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))
- Advice** General underbody component corrosion
- Advice** Rear Exhaust has a minor leak of exhaust gases advise exhaust badly corroded at hangers (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 2255017 (5.2.3 (e))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 2255017 (5.2.3 (e))
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Power steering close to minimum mark (2.1.5 (b) (i))

**MOT #10**

2019-09-10 07:45

MOT test number

865987476222

Result

✓ Passed

- Advice** Both rear trailing arm bushes badly split deteriorated
- Advice** Power steering level minimum
- Advice** Some components corroded
- Advice** Front brake discs inner faces worn, badly corroded
- Advice** Front exhaust deteriorated, rear shield deteriorated and insecure
- Advice** Rear indicators discoloured

MOT #9

2019-09-06 12:03

MOT test number

748656607539

Result

✗ Failed

- Advice** Power steering level minimum
- Advice** Some components corroded
- DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick brake disc worn corroded, full electric (1.1.13 (a) (ii))
- Advice** Front brake discs inner faces worn, badly corroded
- Advice** Front exhaust deteriorated, rear shield deteriorated and insecure
- Advice** Rear indicators discoloured
- Advice** Both rear trailing arm bushes badly split deteriorated

**MOT #8**

2018-10-09 13:08

MOT test number

149466024033

Result

✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened corroded on inner face (1.1.14 (a) (ii))
- Advice** Nearside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Central exhaust heatshield insecure
- Advice** Power steering close to minimum mark (2.1.5 (b) (i))
- Advice** Coil spring corroded both rear (5.3.1 (b) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened slight bind at n/sr and brake pads thin (1.1.14 (a) (ii))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Exhaust system corroded and deteriorated

MOT #7

2017-10-10 16:22

MOT test number

623350856781

Result

✓ Passed

- Advice** Front inner discs corroded
- Advice** Windscreen cracked ns
- Advice** Exhaust badly corroded / hangers broken / shields insecure
- Advice** Steering slight play
- Advice** Osf wheel bearing roughness

**MOT #6** 2016-10-05 13:20**MOT test number** 880023770582**Result** ✓ Passed

- Advice** Windscreen crack ns not affecting drivers view
- Advice** Exhaust hangers broken
- Advice** Both front tyres limit winters 2255017 nsr close to limit/ edges worn / nail osr
- Advice** Trailing arm bushes split separated
- Advice** Rear brakes worn

MOT #5 2015-09-16 07:51**MOT test number** 494823937735**Result** ✓ Passed

- Advice** Both front and nsr tyres worn close to limit 2255017 frontswinter
- Advice** Fan belt noisy
- Advice** Exhaust mounts badly corroded/broken
- Advice** Trailing arm bushes seperating

MOT #4 2014-08-27 17:05**MOT test number** 468119334298**Result** ✓ Passed

- Notice** Child seat fitted not allowing full inspection of adult belt

MOT #3 2013-09-02 11:49**MOT test number** 699205743289**Result** ✓ Passed



MOT #2	2013-09-02 11:49
MOT test number	649355243278
Result	✗ Failed
Pass with rectification	Nearside Headlamp aim too far to the left (1.8)

MOT #1	2012-09-18 13:12
MOT test number	265542262291
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
7 November 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	7 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	SK59HZU
Plate since	2019-03-28
Current registration	SK59HZU
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-24
Last registration	2023-11-06
Complete history	See info



Registration #1	2009-09-24	9 mi
Registration #2	2012-09-18	49.676 mi
Registration #3	2013-09-02	63.954 mi
Registration #4	2014-08-27	73.096 mi
Registration #5	2015-09-16	80.060 mi
Registration #6	2016-10-05	85.047 mi
Registration #7	2017-10-10	90.771 mi
Registration #8	2018-10-09	96.004 mi
Registration #9	2019-09-06	101.436 mi
Registration #10	2020-09-06	106.868 mi
Registration #11	2021-09-06	112.299 mi
Registration #12	2022-09-06	117.730 mi
Registration #13	2023-09-06	123.161 mi
Registration #14	2024-09-06	128.592 mi
Registration #15	2025-09-06	134.023 mi
Registration #16	2026-09-06	139.454 mi
Registration #17	2027-09-06	144.885 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1847 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1755 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	4383179