



MD07GPU

report date: 2024-03-28

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Silver
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg



**MOT history**

MOT #16	2020-08-22 09:33
MOT test number	949159980475
Result	✓ Passed
Next expiry date	2021-08-30

MOT #15	2019-08-27 14:36
MOT test number	265489151856
Result	✓ Passed

MOT #14	2019-08-27 08:48
MOT test number	431016994102
Result	✗ Failed

- Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2018-08-14 16:01
MOT test number	399358870183
Result	✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2018-08-14 08:23**MOT test number** 228837192246**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**MOT #11** 2017-08-26 08:10**MOT test number** 868047133046**Result** ✓ Passed**MOT #10** 2016-08-31 12:43**MOT test number** 492081139946**Result** ✓ Passed**MOT #9** 2015-07-22 14:35**MOT test number** 916051360496**Result** ✓ Passed**MOT #8** 2014-07-11 12:38**MOT test number** 698792094174**Result** ✓ Passed**MOT #7** 2014-07-11 12:38**MOT test number** 345962494149**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #6** 2013-07-30 10:18**MOT test number** 415271213251**Result** ✓ Passed**MOT #5** 2012-06-20 12:04**MOT test number** 287332472147**Result** ✓ Passed**MOT #4** 2012-06-20 12:04**MOT test number** 978642972130**Result** ✗ Failed

Pass with rectification Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Pass with rectification Offside Stop lamp not working (1.2.1b)

MOT #3 2011-07-12 15:58**MOT test number** 525113791174**Result** ✓ Passed**MOT #2** 2011-07-12 15:58**MOT test number** 619363191140**Result** ✗ Failed

Pass with rectification Offside Rear Direction indicators incorrect colour (1.4.A.2f)

Pass with rectification Nearside Rear Direction indicators incorrect colour (1.4.A.2f)

Pass with rectification Offside Rear Stop lamp not working (1.2.1b)

MOT #1 2010-07-12 09:40**MOT test number** 274123790496**Result** ✓ Passed

Notice Nearside front tyre sidewall scrubbed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-08-16
Last registration	2020-08-22
Complete history	See info



Registration #1	2007-08-16	25 mi
Registration #2	2010-07-12	6.054 mi
Registration #3	2011-07-12	9.034 mi
Registration #4	2012-06-20	11.828 mi
Registration #5	2013-07-30	14.550 mi
Registration #6	2014-07-11	16.487 mi
Registration #7	2015-07-22	18.378 mi
Registration #8	2016-08-01	20.315 mi
Registration #9	2017-08-01	22.252 mi
Registration #10	2018-08-01	24.189 mi
Registration #11	2019-08-01	26.126 mi
Registration #12	2020-08-01	28.063 mi
Registration #13	2021-08-01	30.000 mi
Registration #14	2022-08-01	31.937 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	7E54776