




report date: 2024-03-29

General information

Make	CITROEN
Model	C4 PICASSO BLUEHDI VTR PLUS EAT6
Colour	Silver
Year of manufacture	2017
Top speed	117 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	100 g/km
CO2 label	A





## Internet history

## Entry 5

Date	2023-04-26
Pictures	0
Listing price	<a href="#">View report</a>

source: carcraft.co.uk

## Entry 4

Date	2023-04-18
Pictures	23
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## Entry 3

Date	2022-02-22
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk

## Entry 2

Date	2021-11-12
Pictures	18
Listing price	<a href="#">View report</a>



source: yesauto.com

## Entry 1

Date	2021-11-09
------	------------

Pictures	0
Listing price	<a href="#">View report</a>

**source: cargurus.co.uk**



MOT history

MOT expiry date	2024-05-25
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	9
Total items failed	1

MOT #6	2023-05-26 13:44
MOT test number	376502525458
Result	✓ Passed
Next expiry date	2024-05-25

MOT #5	2022-04-15 07:27
MOT test number	476073067134
Result	✓ Passed

MOT #4	2021-05-10 13:36
MOT test number	613050294112
Result	✓ Passed
Advice	Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #3** 2021-05-10 12:10**MOT test number** 754040444532**Result** ✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #2** 2020-05-15 13:13**MOT test number** 244356940771**Result** ✓ Passed

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Tyre slightly damaged/cracking or perishing both sides,perished on sidewalls. (5.2.3 (d) (ii))

**MOT #1** 2020-05-04 06:31**MOT test number** 100865643434**Result** ✓ Passed

- Advice** COVID-19 6 MONTH EXTENSION



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
25 May 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	25 May 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>First licence fee (12 months)</b>	£ 165,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 185,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-05-12
Last registration	2023-05-26
Complete history	<a href="#">See info</a>



Registration #1	2017-05-12	7 mi
Registration #2	2020-05-15	13.535 mi
Registration #3	2021-05-10	14.683 mi
Registration #4	2021-05-10	14.684 mi
Registration #5	2022-05-26	15.277 mi
Registration #6	2022-05-26	15.277 mi
Registration #7	2022-05-26	15.277 mi
Registration #8	2022-05-26	15.277 mi
Registration #9	2022-05-26	15.277 mi
Registration #10	2022-05-26	15.277 mi
Registration #11	2022-05-26	15.277 mi

More info >



Safety ratings

NCAP rating



Video

[see crash video](#)

Dimensions & weight

Width

1826 mm

Height

1611 mm

Length

4428 mm

Wheel base

2785 mm

Kerb weight

1320 kg

Max. allowed weight

1975 kg

Additional information

Fuel tank capacity

55 l

Fuel delivery

Direct Injection

Number of doors

5

Number of seats

5

Number of axles

2

Engine number

JBHD3060067