






report date: 2024-03-29

General information

Make	RENAULT	
Model	TRAFIC SL27 DCI S/R P/V	
Colour	Silver	
Year of manufacture	2012	
Top speed	99 mph	
Gearbox	6 speed Manual	

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Engine capacity	1.996 сс
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.9 mpg



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2021-12-18

Pictures 17

Listing price <u>View report</u>









source: yesauto.com

Entry 1


Date 2021-12-04

Pictures 18

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-02-19
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	8
Total items failed	9

MOT #14	2024-02-20 13:59
MOT test number	904190651980
Result	✓ Passed
Next expiry date	2025-02-19

MOT #13	2024-02-19 11:49
MOT test number	857813059312
Result	X Failed
Fail Nearside Front Anti-roll bar ball joint dust cover no longer prevents the	e ingress of dirt (5.3.4 (b) (ii))

MOT #12	2022-12-01 18:20
MOT test number	788841328847
Result	✓ Passed

MOT #11	2021-12-22 15:19

MOT test number 823982334280 ✓ Passed Result

Advice Vehicle fitted with the following synthetic protective shields, under bonnet and under body obscuring all underside components and /or the vehicle rigidity from visual inspection.

CarCheck.co.uk page 3/12



MOT #10 2021-04-09 13:22

MOT test number 536097664303

Result ✓ Passed

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #9 2021-04-06 11:42

MOT test number 152681982664

Result × Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Brake pipe excessively corroded front to rear (1.1.11 (c))

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Nearside Brake pipe excessively corroded front to rear (1.1.11 (c))

Fail Nearside Front Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

MOT #8 2020-03-19 15:48

MOT test number 952383758237

Result ✓ Passed

MOT #7 2020-03-19 11:16

MOT test number 534448764768

Result × Failed

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

Fail Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt insecure to joint (6.1.7 (g) (ii))

CarCheck.co.uk page 4/12



MOT test number

SH12AJX report date: 2024-03-29

350740447150

MOT #6 2019-03-25 13:36

MOT test number 999030677756

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #5 2018-04-06 08:16

MOT test number 530222481427

Result ✓ Passed

MOT #4 2018-04-05 11:04 MOT test number 281248317105

Result X Failed

Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)

MOT #3 2017-04-11 11:41 MOT test number 771347403417

Result ✓ Passed

MOT #2 2016-04-07 10:29

MOT #1 2015-04-10 11:14

MOT test number 226990605168

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/12



Tax & MOT check



Days left 217

MOT expiry date 19 February 2025

Full MOT history See MOT history

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



_	
Owner	hictory
OWITEL	HIISLUHV

e when motory	
For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-04-13
Last registration	2024-02-20
Complete history	See info



Registration #1	2012-04-13	6 mi
Registration #2	2015-04-10	37.520 mi
Registration #3	2016-04-07	48.020 mi
Registration #4	2017-04-11	60.642 mi
Registration #5	2018-04-05	70.150 mi
Registration #6	2018-04-06	70.151 mi
Registration #7	2019-03-25	81.189 mi
Registration #8	2020-03-19	91.429 mi
Registration #9	2020-03-19	91.429 mi
Registration #10		77,777 44
Registration #11		71,777 66
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 ms

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Additional information

-	
Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	C018034

CarCheck.co.uk page 12/12