



HYUNDAI



DTI7XSC


report date: 2024-03-28

General information

Make	HYUNDAI
Model	TUCSON CRDI PREMIUM SE
Colour	Grey
Year of manufacture	2017
Top speed	114 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	373 Nm at 1.800 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	52.3 mpg
Consumption combined	46.3 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 2


Date	2021-12-14
Pictures	1
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-01-31
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2025-01-28
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	17
Total items failed	6

## MOT #5 2024-01-29 15:18

MOT test number 972758900704

Result ✓ Passed

Next expiry date 2025-01-28

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))

**Advice** TPMS LIGHT ON

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

## MOT #4 2022-12-06 17:22

MOT test number 172834497416

Result ✓ Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened slightly worn. (1.1.14 (a) (ii))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened slightly worn. (1.1.14 (a) (ii))

**MOT #3**

2022-11-25 09:38

**MOT test number**

132760883332

**Result****✗ Failed****Advice** Front Brake disc worn, pitted or scored, but not seriously weakened slightly worn. (1.1.14 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Driver's view Items removed from driver's view prior to test air freshener on interior mirror which would result in MOT FAILURE. (3.1 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened slightly worn. (1.1.14 (a) (ii))**Advice** TPMS warning lamp on indicating incorrect tyre pressure.**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Vehicles internal headlight adjuster altered to recheck lights**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**MOT #2**

2021-07-18 13:16

**MOT test number**

165463775736

**Result****✓ Passed****Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge low on tread 2mm (5.2.3 (e))



MOT #1	2020-07-07 13:58
MOT test number	874548695910
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge measured 1.6mm (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge measured 2.4mm (5.2.3 (e))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
28 January 2025

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	248
<b>MOT expiry date</b>	28 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	I
<b>First licence fee (12 months)</b>	£ 645,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 1.040,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-07-27
Last registration	2024-01-29
Complete history	<a href="#">See info</a>



Registration #1	2017-07-27	23 mi
Registration #2	2020-07-07	26.371 mi
Registration #3	2019-05-29	25.277 mi
Registration #4	2021-07-18	37.876 mi
Registration #5	2019-05-29	25.277 mi
Registration #6	2019-05-29	25.277 mi
Registration #7	2019-05-29	25.277 mi
Registration #8	2019-05-29	25.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	85%
Pedestrian	71%
Safety systems	71%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1850 mm
Height	1650 mm
Length	4475 mm
Wheel base	2670 mm
Kerb weight	1779 kg
Max. allowed weight	2250 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4HAGU527861