





report date: 2024-03-28

General information

Make	PEUGEOT
Model	BOXER HDI 335 L3H2 PROFESSIONAL P/V
Colour	White
Year of manufacture	2014
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	37.6 mpg
Consumption combined	32.4 mpg
CO2 emission	229 g/km
CO2 label	L



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-12

Pictures 16

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

MOT expiry date	2024-11-28
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	24
Total items failed	3

MOT #10	2023-11-29 14:42	
MOT test number	874003773001	
Result	✓ Passed	
Next expiry date	2024-11-28	
Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear wish bone bush (5.3.4 (a) (i))		
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear wish bone bush (5.3.4 (a) (i))		

MOT #9		2023-11-28 11:52
MOT test	number	694333826600
Result		× Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice wish bone	Nearside Front Suspension arm pin or bush worn but not resulting in excess bush (5.3.4 (a) (i))	sive movement rear
MAJOR	Parking brake efficiency below requirements (1.4.2 (a) (i))	
DANGER	OUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
MAJOR	Offside Front Headlamp aim projected beam image is obviously incorrect (4	l.1.2 (c))
Advice bone bush	Offside Front Suspension arm pin or bush worn but not resulting in excessiv (5.3.4 (a) (i))	ve movement rear wish

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #8

MOT test number

Result

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT test number

438360347736

Result

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

DANGEROUS Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT test number

483323139350

Result

Advice (a) (i))

Advice Exhaust mounting defective (6.1.2 (a))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

CarCheck.co.uk page 4/13



MOT test number

BK140CP

report date: 2024-03-28

138677989732

 MOT #5
 2021-05-13 09:52

 MOT test number
 647054426813

Result X Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Pass with rectification Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Exhaust mounting defective (6.1.2 (a))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))

Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #4 2020-04-17 09:09

MOT test number 266273179065

MOT #3 2019-08-29 15:36

Result X Failed

MAJOR Driver's airbag obviously inoperative (7.1.5 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #2 2018-08-07 11:47

MOT test number 510471363761

Result

Passed

Advice Offside Front indicator lens missing or damaged

Minor Windscreen damaged but not adversely affecting driver's view just outside drivers view (3.2 (a) (i))

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1 2017-04-04 11:36

MOT test number 965294271975

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check





Expires: 28 November 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	28 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

Owner history

Owner mistory	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NE UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-04-16
Last registration	2023-11-29
Complete history	See info



Registration #1	2014-04-16	18 mi
Registration #2	2017-04-04	76.893 mi
Registration #3	2018-08-07	90.103 mi
Registration #4	2019-08-29	96.196 mi
Registration #5	2020-04-17	71.372 mi
Registration #6	2021-05-13	109.248 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		9.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	***
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2508 mm
Height	2524 mm
Length	5998 mm
Kerb weight	2101 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	90 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number CarCheck.co.uk	TRJ50737360 page 13/13