



report date: 2024-03-29

General information

Make	VAUXHALL
Model	MOVANO F3500 L3H1 P/C CDTi
Colour	White
Year of manufacture	2016
Top speed	80 mph
0 - 60 mph	14.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	35.0 mpg
Consumption combined	32.0 mpg
CO2 emission	216 g/km
CO2 label	K





Internet history

Entry 1

Date	2022-01-07
Pictures	8
Listing price	View report



source: cargurus.co.uk





MOT history

MOT expiry date	2024-11-21
MOT pass rate	50 %
MOT passed	4
Failed MOT tests	4
Total advice items	6
Total items failed	13

MOT #8	2023-11-17 11:38
MOT test number	520764358453
Result	✓ Passed
Next expiry date	2024-11-21

MOT #7	2023-11-15 18:21
MOT test number	295946624896
Result	✗ Failed
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Rear fog lamp not working (4.5.1 (a) (ii))

MOT #6	2022-11-22 16:46
MOT test number	188021268521
Result	✓ Passed

MOT #5	2022-10-13 10:35
MOT test number	540201748801
Result	✗ Failed
Fail	Nearside Front Service brake excessively binding (1.2.1 (f))

**MOT #4** 2021-01-29 18:06**MOT test number** 719205258441**Result** ✓ Passed**MOT #3** 2021-01-27 09:17**MOT test number** 875549504179**Result** ✗ Failed**Fail** Service brake efficiency below requirements (1.2.2 (a) (i))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. parking brake (1.2.1 (b) (i))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Rear Service brake imbalanced across an axle (1.2.1 (b) (i))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Fail** Nearside Front Upper Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Position lamp light intensity significantly reduced cleaned (4.2.3 (a) (ii))**MOT #2** 2019-07-26 08:45**MOT test number** 807161886326**Result** ✓ Passed**Advice** Vehicles internal headlight adjuster altered to recheck lights**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #12019-07-26 08:45

MOT test number206784350722

Result

Failed

- Pass with rectification

Windscreen washer provides insufficient washer liquid (3.5 (a))
- Pass with rectification

Headlamp aim too low (4.1.2 (a))
- Advice

Vehicles internal headlight adjuster altered to recheck lights
- Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Pass with rectification

Offside Side repeater not working (4.4.1 (a) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
21 November 2024

Tax status	Valid until 1 February
Days left	277
MOT expiry date	21 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	FD16LXN
Plate since	2019-03-29
Current registration	FD16LXN
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2016-07-29
Last registration	2023-11-17
Complete history	See info



Registration #1	2016-07-29	13 mi
Registration #2	2019-07-26	9.041 mi
Registration #3	2019-07-26	9.041 mi
Registration #4	2021-01-27	14.983 mi
Registration #5	2021-01-29	14.983 mi
Registration #6	2023-11-17	15.277 mi
Registration #7	2023-11-17	15.277 mi
Registration #8	2023-11-17	15.277 mi
Registration #9	2023-11-17	15.277 mi
Registration #10	2023-11-17	15.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight

Width	2470 mm
Height	2270 mm
Length	6180 mm
Kerb weight	1599 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	M9T -C181343 LWL