



General information

Make	BMW
Model	216 216D SPORT GRAN TOURER
Colour	Red
Year of manufacture	2015
Top speed	119 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.496 cc
Cylinders	3
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-01-28
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-05-12
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	30
Total items failed	3

MOT #11	2024-04-17 09:02
MOT test number	501606776952
Result	✓ Passed
Next expiry date	2025-05-12
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Offside Rear Tyre worn close to legal limit/worn on edge On edges (5.2.3 (e))
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge On edges (5.2.3 (e))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #10	2023-05-04 12:42
MOT test number	339535019062
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Play in steering rack inner joint(s)
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #9**

2023-05-02 15:44

**MOT test number**

521326420171

**Result**

✗ Failed

- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**MOT #8**

2022-05-13 10:05

**MOT test number**

509953377998

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively Both (1.1.14 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7**

2022-04-06 09:24

**MOT test number**

888607224704

**Result**

✓ Passed

- Advice** Pad warning light on dash
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edges worn, centre 2.8 mm (5.2.3 (e))
- Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #6** 2022-04-05 12:25**MOT test number** 204306942310**Result** ✗ Failed**Fail** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm both edges (5.2.3 (e))**Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Pad warning light on dash**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner and outer edges worn, centre 2.8 mm (5.2.3 (e))**Fail** Nearside Front Brake hose excessively twisted (1.1.12 (b) (ii))**MOT #5** 2021-04-06 11:00**MOT test number** 302082351518**Result** ✓ Passed**MOT #4** 2020-07-24 13:38**MOT test number** 435428682802**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Engine covers & undertrays fitted**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2020-07-21 07:35**MOT test number** 374054159330**Result** ✓ Passed



MOT #2	2019-07-24 10:24
MOT test number	881044762929
Result	✓ Passed
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1	2018-07-18 10:08
MOT test number	103388172816
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
12 May 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	338
<b>MOT expiry date</b>	12 May 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-06-01
Last registration	2024-04-17
Complete history	<a href="#">See info</a>



Registration #1	2015-06-01	26 mi
Registration #2	2018-07-18	19.996 mi
Registration #3	2019-07-24	25.835 mi
Registration #4	2020-07-21	30.694 mi
Registration #5	2020-07-24	30.698 mi
Registration #6	2020-07-24	30.698 mi
Registration #7	2021-04-06	30.913 mi
Registration #8	2021-04-06	30.913 mi
Registration #9	2021-04-06	30.913 mi
Registration #10	2021-04-06	30.913 mi
Registration #11	2021-04-06	30.913 mi
Registration #12	2021-04-06	30.913 mi
Registration #13	2021-04-06	30.913 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1800 mm
Height	1612 mm
Length	4556 mm
Wheel base	2780 mm
Kerb weight	1470 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	30019216