



RENAULT

**BX63HLR**

report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM DCI
Colour	Silver
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	12.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg





Internet history

Entry 1

Date	2021-08-14
Pictures	10
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history****MOT #10**

2024-03-06 16:16

**MOT test number**

211420645733

**Result****✗ Failed****Fail** Offside Rear Stop lamp(s) emits other than a steady red light Lens cracked (4.3.3 (a) (ii))**Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Windscreen washer not working (3.5 (a))**Fail** Nearside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Headlamp aim unable to be tested (4.1.2 (b))**Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Offside Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**MOT #9**

2023-03-02 12:56

**MOT test number**

500010274166

**Result****✓ Passed****Advice** Play in steering rack inner joint(s)**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #8** 2023-02-28 11:34**MOT test number** 789204743930**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Play in steering rack inner joint(s)**MOT #7** 2021-09-07 13:42**MOT test number** 162087118152**Result** ✓ Passed**MOT #6** 2020-10-23 08:19**MOT test number** 193095073298**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tyre is worn to 1.98mm. Tyre is also slightly cracked. (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Both front tyres are wearing slightly on outer edges**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2019-10-30 14:40**MOT test number** 642077983875**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2018-10-05 10:36**MOT test number** 109870391640**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))**Advice** Nearside Rear Outer Tyre side wall is cracked and perished but no ply or cords are exposed at present**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2017-09-28 14:12**MOT test number** 425091239171**Result** ✓ Passed**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Advice** 29% front brake imbalance.**MOT #2** 2016-09-27 16:35**MOT test number** 272627523424**Result** ✓ Passed**Advice** Under body trays fitted**Advice** Child seats fitted to near side and offside rear seats not able to check adult belt**MOT #1** 2016-09-20 16:07**MOT test number** 511308957544**Result** ✗ Failed**Advice** Child seats fitted to near side and offside rear seats not able to check adult belt**Fail** Nearside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Advice** Under body trays fitted



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>REDACTED</b>
Plate since	2019-09-29
Current registration	<b>REDACTED</b>
Plate since	2019-09-29

More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2013-09-30
Last registration	2024-03-06
Complete history	<a href="#">See info</a>



Registration #1	2013-09-30	22 mi
Registration #2	2016-09-20	26.340 mi
Registration #3	2016-09-27	26.654 mi
Registration #4	2017-09-28	36.459 mi
Registration #5	2018-10-05	46.474 mi
Registration #6	2019-10-30	55.975 mi
Registration #7	2020-03-20	56.277 mi
Registration #8	2020-03-20	56.277 mi
Registration #9	2020-03-20	56.277 mi
Registration #10	2020-03-20	56.277 mi
Registration #11	2020-03-20	56.277 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1808 mm
Height	1471 mm
Length	4295 mm
Wheel base	2703 mm
Kerb weight	1215 kg
Max. allowed weight	1813 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D144369