



LRI3ZGJ

report date: 2024-03-28

General information

Make	MINI
Model	COOPER S AUTO JOHN COOPER WORKS
Colour	Orange
Year of manufacture	2013
Top speed	148 mph
0 - 60 mph	6.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	211 BHP
Max. torque	260 Nm at 5.500 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.1 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.8 mpg
CO2 emission	153 g/km
CO2 label	G






Internet history

Entry 2

Date 2023-12-13

Pictures 6




source: g3remarketing.co.uk

Entry 1

Date 2021-12-16

Pictures 38

Listing price [View report](#)



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-04
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	10
Total items failed	2

MOT #11	2023-12-13 16:51
MOT test number	727560853809
Result	✓ Passed
Next expiry date	2025-01-04
Advice	Offside Front jacking block missing
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Front Play in steering rack inner joint(s)
Advice	Nearside Front Inner Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10	2023-01-05 10:17
MOT test number	863602662146
Result	✓ Passed

MOT #9	2021-12-20 11:24
MOT test number	840409315367
Result	✓ Passed

**MOT #8** 2020-11-24 15:10**MOT test number** 717890102322**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner tread (5.2.3 (e))**Advice** Engine covers and under trays obscuring some components**Advice** Offside Front Tyre worn close to legal limit/worn on edge inner tread (5.2.3 (e))**MOT #7** 2019-11-19 16:48**MOT test number** 232969942679**Result** ✓ Passed**Advice** Engine covers and under trays obscuring some components**MOT #6** 2019-11-19 16:48**MOT test number** 645547569915**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Engine covers and under trays obscuring some components**Pass with rectification** Front Windscreen washer not working (3.5 (a))**MOT #5** 2018-11-14 17:55**MOT test number** 221710444195**Result** ✓ Passed**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**MOT #4** 2017-11-24 15:34**MOT test number** 576882042879**Result** ✓ Passed



MOT #3	2016-12-10 13:48
MOT test number	668844152901
Result	✓ Passed
MOT #2	2016-10-28 14:39
MOT test number	750743551029
Result	✓ Passed
MOT #1	2016-04-27 08:28
MOT test number	714469812954
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
4 January 2025

Tax status	Valid until 1 February
Days left	279
MOT expiry date	4 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-05-01
Last registration	2023-12-13
Complete history	See info



Registration #1	2013-05-01	12 mi
Registration #2	2016-04-27	18.042 mi
Registration #3	2016-10-28	21.240 mi
Registration #4	2016-12-10	21.248 mi
Registration #5	2017-11-24	27.152 mi
Registration #6	2018-11-14	31.088 mi
Registration #7	2019-11-19	37.672 mi
Registration #8	2020-05-20	45.277 mi
Registration #9	2020-05-20	45.277 mi
Registration #10	2020-05-20	45.277 mi
Registration #11	2020-05-20	45.277 mi
Registration #12	2020-05-20	45.277 mi
Registration #13	2020-05-20	45.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1913 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1130 kg
Max. allowed weight	1610 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Engine number

A511J527