





report date: 2024-03-28

General information

Make	FORD
Model	S-MAX ZETEC TDCI
Colour	Black
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date	2021-07-13	
Pictures	1	
Listing price	View report	



source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-07-27
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	15
Total items failed	4

MOT #15		2023-07-28 13:28
MOT test	number	612898937894
Result		✓ Passed
Next expi	y date	2024-07-27
Advice	Nearside Front Outer Tyre worn close to legal limit/worn on edge edge v	worn (5.2.3 (e))
Advice	Offside Front Coil spring corroded (5.3.1 (b) (i))	
Advice	Rear suspension components and mounting areas corroded	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #14		2022-07-15 08:32
MOT test	number	975044422830
Result		✓ Passed
Advice	Undertrays fitted now allowing full inspection of the vehicle	
Advice (5.2.3 (e))	Nearside Front Tyre worn close to legal limit/worn on edge @3mm and	wearing on the outer edge

MOT #13	2021-07-15 14:02
MOT test number	837205900040
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #12 2020-11-27 15:11

MOT test number 548652559735

Result ✓ Passed

MOT #11 2020-11-27 09:59

MOT test number 158178662044

Result X Failed

Fail Offside Front Axle swivel pins and bushes swivel pin and/or bush excessively worn rear exlae mounting bush (5.1.2 (b) (i))

Fail Nearside Front Axle swivel pins and bushes swivel pin and/or bush excessively worn rear axle bush (5.1.2 (b) (i))

MOT #10 2019-05-21 08:14

MOT test number 506122889070

Result ✓ Passed

MOT #9 2018-05-30 14:58

MOT test number 836163112076

Result \(\sqrt{Passed} \)

MOT #8 2018-05-30 08:54

MOT test number 654372136496

Result X Failed

Fail Offside Front Service brake lagging in operation (1.2.1 (d))

Advice Rear Brake pad(s) wearing thin ready now (1.1.13 (a) (ii))

Fail Front Service brake excessively fluctuating (1.2.1 (e))

Advice Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #7		2017-05-05 11:32
MOT test	number	868102308868
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Front brake discs corroded on inside surfaces	
Advice	Child Seat fitted not allowing full inspection of adult belt	

MOT #6		2016-05-09 12:39
MOT test	number	252438064947
Result		✓ Passed
MOT #5		2015-05-01 11:26
MOT test	number	838251525193
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)	

MOT #4	2014-05-12 13:33
MOT test number	455672534108
Result	✓ Passed
Advice Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #3	2013-03-01 10:39
MOT test number	105240663438
Result	✓ Passed
Notice BOTH FRONT TYRES SHOWING WEAR	

CarCheck.co.uk page 5/13



 MOT #2
 2011-12-22 09:50

 MOT test number
 649456451365

 Result
 ✓ Passed

 MOT #1
 2010-12-20 14:49

 MOT test number
 462254650312

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	27 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	

,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	NK NE
Plate since	
Current registration	NK.
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-31
Last registration	2023-07-28
Complete history	See info



Registration #1	2008-03-31	23 mi
Registration #2	2010-12-20	28.329 mi
Registration #3	2011-12-22	34.373 mi
Registration #4	2013-03-01	41.506 mi
Registration #5	2014-05-12	47.759 mi
Registration #6	2015-05-01	54.223 mi
Registration #7	2016-05-09	61.802 mi
Registration #8	2017-05-05	67.688 mi
Registration #9	2018-05-30	72.102 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1897 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1

Number of axles 2

Engine number 8D05019