



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD I-DTEC EX
Colour	Silver
Year of manufacture	2009
Top speed	132 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F







Internet history

Entry 1

Date	2021-10-03
Pictures	17
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-03-24
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	36
Total items failed	10

MOT #18	2024-03-22 13:50
MOT test number	886038585409
Result	✓ Passed
Next expiry date	2025-03-24
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #17	2024-03-20 11:51
MOT test number	124732465989
Result	✗ Failed
Fail	Offside Front Headlamp aim too high (4.1.2 (a))
Advice	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Fail	Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #16**

2023-03-02 12:44

MOT test number

843086452411

Result

✓ Passed

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 29% (1.2.1 (b) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15

2022-03-25 10:42

MOT test number

700506388405

Result

✓ Passed

Advice Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14

2022-03-25 10:42

MOT test number

591550842971

Result

✗ Failed

Pass with rectification Central Rear Fuel tank exhaust shield missing where fitted as original equipment creating a risk of fire (6.1.3 (e))

Advice Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2021-03-25 11:44

MOT test number

969919108211

Result

✓ Passed

- Advice** Under-body surface corrosion
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Suspension components corroded
- Advice** Rear Suspension components corroded
- Advice** Front Subframe slightly corroded
- Advice** Rear Subframe corroded

MOT #12

2021-03-19 09:44

MOT test number

552511870099

Result

✗ Failed

- Advice** Front Subframe slightly corroded
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Rear Subframe corroded
- Advice** Under-body surface corrosion
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Advice** Front Suspension components corroded
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Rear Suspension components corroded
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #11** 2020-01-23 13:37**MOT test number** 282376262310**Result** ✓ Passed**MOT #10** 2019-01-19 11:55**MOT test number** 941048699273**Result** ✓ Passed

- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge uneven wear (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge uneven wear (5.2.3 (e))
- Advice** Engine oil low

MOT #9 2019-01-16 10:00**MOT test number** 685447284910**Result** ✗ Failed

- Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge uneven wear (5.2.3 (e))
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Engine oil low
- Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge uneven wear (5.2.3 (e))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #8 2018-01-15 10:00**MOT test number** 736871601012**Result** ✓ Passed

**MOT #7** 2018-01-11 16:10**MOT test number** 506949051173**Result** ✗ Failed**Fail** Fuel cap/sealing device missing (7.2.4a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #6** 2016-10-28 13:08**MOT test number** 368375161127**Result** ✓ Passed**MOT #5** 2015-09-01 14:45**MOT test number** 185855956372**Result** ✓ Passed**MOT #4** 2015-09-01 12:17**MOT test number** 142080468074**Result** ✗ Failed**Fail** Rear registration plate character(s) laid out in an incorrect format (6.3.4f)**Fail** Front registration plate character(s) laid out in an incorrect format (6.3.4f)**MOT #3** 2014-09-19 16:48**MOT test number** 409652164238**Result** ✓ Passed**MOT #2** 2013-10-29 17:04**MOT test number** 555982903369**Result** ✓ Passed



MOT #1	2012-10-29 09:43
MOT test number	599143702318
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
24 March 2025

Tax status	Valid until 1 October
Days left	156
MOT expiry date	24 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-11-19
Last registration	2024-03-22
Complete history	See info



Registration #1	2009-11-19	11 mi
Registration #2	2012-10-29	27.903 mi
Registration #3	2013-10-29	38.528 mi
Registration #4	2014-09-19	43.834 mi
Registration #5	2015-09-01	44.157 mi
Registration #6	2015-09-01	44.157 mi
Registration #7	2016-10-28	45.982 mi
Registration #8	2018-01-11	48.422 mi
Registration #9	2018-01-15	48.422 mi
Registration #10	2019-01-16	64.766 mi
Registration #11	2019-01-16	64.766 mi
Registration #12	2019-01-16	64.766 mi
Registration #13	2019-01-16	64.766 mi
Registration #14	2019-01-16	64.766 mi
Registration #15	2019-01-16	64.766 mi
Registration #16	2019-01-16	64.766 mi
Registration #17	2019-01-16	64.766 mi
Registration #18	2019-01-16	64.766 mi
Registration #19	2019-01-16	64.766 mi
Registration #20	2019-01-16	64.766 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	79%
Pedestrian	54%
Safety systems	86%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4725 mm
Wheel base	2705 mm
Max. allowed weight	2030 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	1007608