





report date: 2024-03-28

### General information

Make	VOLVO	
Model	S90 D4 MOMENTUM	
Colour	Silver	
Year of manufacture	2018	
Top speed	140 mph	
0 - 60 mph	7.9 seconds	
Gearbox	8 speed automatic	

# Engine & fuel consumption

Power	190 BHP	
Max. torque	400 Nm at 2.500 rpm	
Engine capacity	1.969 сс	
Cylinders	4	
Fuel type	Diesel	
Consumption city	53.3 mpg	
Consumption extra urban	72.4 mpg	
Consumption combined	64.2 mpg	
CO2 emission	116 g/km	
CO2 label	С	



CarCheck.co.uk page 1/11



report date: 2024-03-28

# Internet history


#### Entry 1

Date 2021-08-11

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

# **MOT** history

MOT expiry date	2024-12-19
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	14
Total items failed	2

MOT #4		2023-12-20 11:39
MOT test	number	444177483684
Result		✓ Passed
Next expi	ry date	2024-12-19
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge shoulder (5.2.3 (e))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge shoulder (5.2.3 (e))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



report date: 2024-03-28

**MOT** #3 2023-12-20 11:29 661037328857 **MOT** test number Result × Failed Fail Windscreen washer not working (3.5 (a)) **Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge shoulder (5.2.3 (e)) Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt Power steering inoperative and steering adversely affected (2.1.5 (c) (ii)) Fail **Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge shoulder (5.2.3 (e)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2	2022-11-21 10:33
MOT test number	437954604336
Result	✓ Passed
MOT #1	2021-10-08 12:26
MOT test number	257906445088
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

### Tax & MOT check





Expires: 19 December 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	19 December 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	
manus .	
***************************************	
***************************************	
manus .	
***************************************	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	UK NK
Finite since	WW. PL. PI
Current registration	JK UK
Made since	
	More info >
	11010 11110 /

CarCheck.co.uk page 8/11



LO18MDV report date: 2024-03-28

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



LO18MDV report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2018-07-31
Last registration	2023-12-20
Complete history	See info



Registration #1	2018-07-31	12 mi
Registration #2		11.777 es
Registration #3	2021-10-08	52.662 mi
Registration #4		11.777 es
Registration #5		11.777 es
Designation #6		

Registration #6

More info >

CarCheck.co.uk page 10/11



LO18MDV report date: 2024-03-28

# Car features

50225	Air conditioning
50295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	see crash video



# Dimensions & weight

Width	2019 mm
Height	1443 mm
Length	4963 mm
Wheel base	2941 mm
Kerb weight	1680 kg
Max. allowed weight	2270 kg

# Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page	e 11/11