



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D DRIVE SE LUX
Colour	Blue
Year of manufacture	2011
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	57.7 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-06-30
Pictures	23
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-31
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	11
Total items failed	9

MOT #15	2023-07-17 09:18
MOT test number	452330137620
Result	✓ Passed
Next expiry date	2024-07-31

MOT #14	2022-07-01 11:57
MOT test number	161194146511
Result	✓ Passed

MOT #13	2021-07-16 10:43
MOT test number	651379719046
Result	✓ Passed

MOT #12	2021-06-25 10:52
MOT test number	663406874455
Result	✗ Failed

- Fail** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Trailer electrical socket (13 pin) not operating the trailer lamps as intended (4.10 (c) (i))
- Advice** Front Service brake fluctuating, but not excessively discs (1.2.1 (e))

**MOT #11** 2020-08-01 10:21**MOT test number** 557996522217**Result** ✓ Passed**MOT #10** 2019-10-21 14:44**MOT test number** 536811821641**Result** ✓ Passed**MOT #9** 2019-10-18 07:39**MOT test number** 320514759802**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #8** 2018-10-15 12:44**MOT test number** 762317223353**Result** ✓ Passed**MOT #7** 2017-10-06 10:29**MOT test number** 633711695539**Result** ✓ Passed**Advice** Offside Front tyre perishing**Advice** Rear tyres perishing**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #6** 2017-10-05 15:19**MOT test number** 526253686089**Result** ✗ Failed**Fail** Nearside Headlamp aim too low (1.8)**Advice** Offside Front tyre perishing**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Rear tyres perishing**Fail** Offside Headlamp aim too low (1.8)**MOT #5** 2016-10-20 10:41**MOT test number** 850679069774**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #4** 2015-10-26 14:29**MOT test number** 509168735101**Result** ✓ Passed**MOT #3** 2015-02-13 11:46**MOT test number** 265354145001**Result** ✓ Passed**MOT #2** 2015-02-11 09:22**MOT test number** 185032645080**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Fail** Nearside Front coil spring broken (2.4.C.1a)



MOT #1	2014-02-28 10:56
MOT test number	138649054420
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
31 July 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-02
Last registration	2023-07-17
Complete history	See info



Registration #1	2011-03-02	13 mi
Registration #2	2014-02-28	22.208 mi
Registration #3	2015-02-11	26.582 mi
Registration #4	2015-02-13	26.606 mi
Registration #5	2015-10-26	30.187 mi
Registration #6	2016-10-20	34.997 mi
Registration #7	2017-10-05	37.475 mi
Registration #8	2017-10-06	37.480 mi
Registration #9	2018-10-15	40.914 mi
Registration #10	2019-05-20	45.377 mi
Registration #11	2019-05-20	45.377 mi
Registration #12	2019-05-20	45.377 mi
Registration #13	2019-05-20	45.377 mi
Registration #14	2019-05-20	45.377 mi
Registration #15	2019-05-20	45.377 mi
Registration #16	2019-05-20	45.377 mi
Registration #17	2019-05-20	45.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1437 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1760212