





report date: 2024-03-28

### General information

Make	ABARTH
Model	500 ABARTH
Colour	Grey
Year of manufacture	2014
Top speed	129 mph
0 - 60 mph	7.9 seconds
Gearbox	5 speed Manual

# Engine & fuel consumption

Power	135 BHP
Max. torque	180 Nm at 2.500 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	43.5 mpg
CO2 emission	155 g/km
CO2 label	G



CarCheck.co.uk page 1/12



YK14GMY

report date: 2024-03-28

# Internet history

# Entry 3


Date 2023-02-11

Pictures 19

Listing price <u>View report</u>









source: autotrader.co.uk

#### Entry 2

Date	2021-01-29	
Pictures	1	
Listing price	View report	



source: autoonline.co.uk

#### Entry 1

Date	2021-01-29
Pictures	30
Listing price	View report









source: yesauto.com

CarCheck.co.uk page 2/12



YK14GMY

report date: 2024-03-28

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

MOT expiry date	2025-04-14
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	11
Total items failed	8

MOT #11	2024-04-15 14:46
MOT test number	426746276675
Result	✓ Passed
Next expiry date	2025-04-14

MOT #10	2024-04-15 10:59
MOT test number	863857291438
Result	<b>X</b> Failed
Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #9	2023-02-15 18:08
MOT test number	882037492481
Result	✓ Passed

MOT #8	2022-03-18 08:27
MOT test number	936434840865
Result	<b>✓</b> Passed

MOT #7	2021-03-10 16:54
MOT test number	887897140042
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #6 2021-03-10 11:49

MOT test number 100083115935

**Result** X Failed

Fail Nearside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

**Fail** Offside Front Macpherson strut attachment bracket/mounting insecure and impairing directional stability (5.3.3 (a) (ii))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**Fail** Offside Rear Shock absorbers has an excessively worn bush (5.3.2 (c))

**Fail** Nearside Front Macpherson strut attachment bracket/mounting insecure and impairing directional stability (5.3.3 (a) (ii))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #5 2020-03-24 11:25

MOT test number 918534255372

Advice Exhaust back box outer skin corroded

(ii))

Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened both rears (1.1.14 (a)

Advice Front Inner Brake disc worn, pitted or scored, but not seriously weakened both fronts (1.1.14 (a)

(ii))

MOT #4 2020-03-20 14:25

**MOT test number** 700081789042

**Result** X Failed

**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

**Advice** Nearside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))

CarCheck.co.uk page 4/12



MOT #3 2019-03-19 12:45

**MOT test number** 317107529889

**Result** ✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2018-03-13 15:36

**MOT test number** 333359277606

**Result** ✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1 2017-03-06 11:18

MOT test number 516538460857

**Result** 
✓ Passed

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 August
Days left	93
MOT expiry date	14 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this ABARTH. See if, where and when this ABARTH had damage and the car repair costs. We also check if this ABARTH was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra ABARTH salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this ABARTH in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

Plate since

YK14GMY

report date: 2024-03-28

For how long did the current and previous owner(s) have this ABARTH? How many owne have? Check it in the premium report and see all owner registrations. Download the full		
HARMAN CO. C.		
***************************************		
*************		
HERENE STATE OF THE STATE OF TH		
***************************************		
HEREE STATE OF THE		
	More info >	
Plate changes		
Cas in this phase is this ADADTU had different a week as plates		

See in this check if this ABARTH had different number plates.

More info >

CarCheck.co.uk page 9/12



Finance check

Check if this ABARTH is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this ABARTH has been settled.

If not, and you buy this ABARTH then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this ABARTH is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-03-25
Last registration	2024-04-15
Complete history	See info



Registration #1	2014-03-25	9 mi
Registration #2	2017-03-06	19.609 mi
Registration #3	2018-03-13	30.136 mi
Registration #4	2019-03-19	44.461 mi
Registration #5	2020-03-20	58.165 mi
Registration #6	2020-03-24	58.225 mi
Registration #7		9.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		D.777 es

More info >

CarCheck.co.uk page 11/12



# Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3657 mm
Wheel base	2300 mm
Kerb weight	1035 kg
Max. allowed weight	1425 kg

# Additional information

Fuel tank capacity	35 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	1883740

CarCheck.co.uk page 12/12