



report date: 2024-03-28

General information

Make	CITROEN
Model	BERLINGO HDI VT
Colour	Silver
Year of manufacture	2009
Top speed	94 mph
0 - 60 mph	17.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	185 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	56.5 mpg
Consumption combined	49.6 mpg
CO2 emission	150 g/km
CO2 label	F





MOT history

MOT expiry date	2024-07-05
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	24
Total items failed	7

MOT #16	2023-07-06 08:11
MOT test number	349662902870
Result	✓ Passed
Next expiry date	2024-07-05
Advice	Spare tyre defective flat tyre
Advice	Rear exhaust heat shield insecure
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #15	2023-07-06 08:11
MOT test number	968188309426
Result	✗ Failed
Advice	Rear exhaust heat shield insecure
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Spare tyre defective flat tyre
Pass with rectification	Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #14**

2022-06-28 07:46

MOT test number

468153083301

Result

✓ Passed

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #13

2022-06-28 07:46

MOT test number

855231647267

Result

✗ Failed

Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

Pass with rectification Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #12

2021-05-12 13:58

MOT test number

998473392994

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Battery warning light on

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2021-05-11 14:05**MOT test number** 404786787681**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Oil leaking excessively from engine (8.4.1 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Battery warning light on**MOT #10** 2019-05-07 14:34**MOT test number** 420357502480**Result** ✓ Passed**MOT #9** 2019-05-07 14:34**MOT test number** 570802921752**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #8** 2018-05-24 11:18**MOT test number** 405682025394**Result** ✓ Passed**MOT #7** 2018-05-23 10:21**MOT test number** 500655573932**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #6** 2017-05-22 08:25**MOT test number** 114584578607**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-04-08 08:49**MOT test number** 270351112082**Result** ✓ Passed**MOT #4** 2015-06-05 09:22**MOT test number** 346236055121**Result** ✓ Passed**MOT #3** 2014-07-10 15:01**MOT test number** 707731994164**Result** ✓ Passed**MOT #2** 2013-02-15 09:32**MOT test number** 818456643032**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2012-02-09 09:53**MOT test number** 135760042484**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
5 July 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	5 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX
XXXXXXXXXX	XXXXXX

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-09-29
Current registration	XXXXX
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-01
Last registration	2023-07-06
Complete history	See info



Registration #1	2009-03-01	23 mi
Registration #2	2012-02-09	36.470 mi
Registration #3	2013-02-15	47.466 mi
Registration #4	2014-07-10	57.674 mi
Registration #5	2015-06-05	64.049 mi
Registration #6	2016-04-08	71.145 mi
Registration #7	2017-05-22	83.658 mi
Registration #8	2018-05-23	90.654 mi
Registration #9	2018-05-24	90.654 mi
Registration #10	2019-05-22	90.654 mi
Registration #11	2019-05-22	90.654 mi
Registration #12	2019-05-22	90.654 mi
Registration #13	2019-05-22	90.654 mi
Registration #14	2019-05-22	90.654 mi
Registration #15	2019-05-22	90.654 mi
Registration #16	2019-05-22	90.654 mi
Registration #17	2019-05-22	90.654 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1407 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBBU3099403