



BD60VRC

report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	CADDY C20 TDI
Colour	Blue
Year of manufacture	2010
Top speed	104 mph
0 - 60 mph	12.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	101 BHP
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	48.7 mpg





Internet history

Entry 1

Date	2021-10-08
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-08
MOT pass rate	75 %
MOT passed	9
Failed MOT tests	3
Total advice items	17
Total items failed	6

MOT #12 2023-12-05 15:07

MOT test number 496507875588

Result ✓ Passed

Next expiry date 2024-12-08

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Rear exhaust silencer is in poor condition

MOT #11 2023-12-05 09:35

MOT test number 558309721532

Result ✗ Failed

MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

Advice Rear exhaust silencer is in poor condition

MAJOR Windscreen washer provides insufficient washer liquid retaining clip missing that holds the pipe on to the washer pump (3.5 (a))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #10 2022-12-09 18:13

MOT test number 494277007112

Result ✓ Passed

**MOT #9** 2022-12-07 14:08**MOT test number** 374059827634**Result** ✗ Failed**MAJOR** Offside Headlamp aim too low (4.1.2 (a))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm 235 40 18 (5.2.3 (e))**MAJOR** Nearside Headlamp aim too low (4.1.2 (a))**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm 235 40 18 (5.2.3 (e))**MOT #8** 2021-11-10 08:11**MOT test number** 802363178301**Result** ✓ Passed**MOT #7** 2021-05-01 13:33**MOT test number** 200173070770**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))**MOT #6** 2017-10-18 09:51**MOT test number** 281122244325**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin both o/s & n/s inner (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened both o/s & n/s corroded on surface (3.5.1i)



MOT #5	2016-11-12 12:03
---------------	------------------

MOT test number	475577115174
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2015-11-06 16:31
---------------	------------------

MOT test number	311429290362
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2014-11-14 11:51
---------------	------------------

MOT test number	737158714302
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #2	2013-11-19 11:21
---------------	------------------

MOT test number	716823723357
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2013-11-16 12:56
---------------	------------------

MOT test number	899560723304
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Parking brake lever defective so that it cannot be satisfactorily operated (3.1.3c)
-------------	---

Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	--

Fail	Nearside Front Front position lamp(s) not working (1.1.A.3b)
-------------	--

Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
-------------	---

Fail	Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
-------------	--

Fail	Offside Front Front position lamp(s) not working (1.1.A.3b)
-------------	---



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
8 December 2024

Tax status		Valid until 1 December
Days left		215
MOT expiry date		8 December 2024
Full MOT history		See MOT history



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BD60VRC
Plate since	2024-03-29
Current registration	 BD60VRC
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-12-14
Last registration	2023-12-05
Complete history	See info



Registration #1	2010-12-14	24 mi
Registration #2	2013-11-16	45.149 mi
Registration #3	2013-11-19	45.149 mi
Registration #4	2014-11-14	53.672 mi
Registration #5	2015-11-06	74.952 mi
Registration #6	2016-11-12	87.406 mi
Registration #7	2017-10-18	123.844 mi
Registration #8	2018-05-22	151.277 mi
Registration #9	2019-05-22	151.277 mi
Registration #10	2020-05-22	151.277 mi
Registration #11	2021-05-22	151.277 mi
Registration #12	2022-05-22	151.277 mi
Registration #13	2023-05-22	151.277 mi
Registration #14	2023-12-05	151.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2062 mm
Height	1836 mm
Length	4876 mm
Kerb weight	1560 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	2
Engine number	CAY 447731