





report date: 2024-03-29

### General information

Make	RENAULT
Model	MEGANE DYNAMIQUE TOMTOM ENERGY DCI S/S
Colour	White
Year of manufacture	2013
Top speed	118 mph
0 - 100 km/h	12.1 seconds
0 - 60 mph	12.1 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	72.4 mpg
Consumption extra urban	88.3 mpg
Consumption combined	80.7 mpg
CO2 emission	90 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

#### Entry 1

Date	2021-02-04
Pictures	1
Listing price	<u>View report</u>



source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

N/I	$\alpha$		IIC.	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-01-25
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	17
Total items failed	2

MOT #12	2024-01-23 12:32
MOT test number	185737672259
Result	<b>✓</b> Passed
Next expiry date	2025-01-25
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #11		2023-01-26 12:00
MOT test	number	676540516842
Result		<b>✓</b> Passed
Advice	Offside Front Outer cv boot weeping	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #10		2023-01-25 12:28
MOT test	number	680566174836
Result		<b>×</b> Failed
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Offside Front Outer cv boot weeping	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/12



Result

**HK630NO** 

report date: 2024-03-29

× Failed

MOT #9 2022-01-26 13:49

MOT test number 499519321919

Result \rightarrow Passed

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #8 2021-12-23 15:28

MOT test number 378242086471

**MAJOR** Headlamp aim not tested both headlamps inoperative (4.1.2 (b))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MAJOR** Headlamp not working on dipped beam both (4.1.1 (a) (ii))

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MAJOR** Front Position lamp not working both (4.2.1 (a) (ii))

MOT #7 2020-11-09 10:06

**MOT test number** 410919635705

Result \( \sqrt{Passed} \)

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #6 2020-11-09 10:06

**MOT test number** 271858605637

Result X Failed

**Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5 2019-11-26 09:20

**MOT test number** 160171250528

MOT #4 2018-12-03 12:29

**MOT test number** 595410141073

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2018-01-03 15:00

**MOT test number** 818356931462

**Result** ✓ Passed

MOT #2 2018-01-03 10:42

**MOT test number** 514533407671

**Result** X Failed

**Fail** Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #1 2017-01-04 12:06

**MOT test number** 203078513140

Result \rightarrow Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

#### Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	25 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



report date: 2024-03-29

#### Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

#### Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

## Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
manage of the same	
***************************************	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	EK UK
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

#### Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-12-31
Last registration	2024-01-23
Complete history	See info



Registration #1	2013-12-31	11 mi
Registration #2	2017-01-04	5.910 mi
Registration #3	2018-01-03	7.656 mi
Registration #4	2018-01-03	7.656 mi
Registration #5	2018-12-03	17.992 mi
Registration #6	2019-11-26	33.916 mi
Registration #7	2020-11-09	39.265 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		D.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-29

## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1804 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1805 kg

### Additional information

Fuel tank capacity	60 I	
Fuel delivery	Direct Injection	
Number of doors	3	
Number of seats CarCheck.co.uk	5 page 1	12/12

Number of axles2Engine numberD156857