



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES-BENZ
Model	CLK CLK200K SPORT
Colour	Silver
Year of manufacture	-
Top speed	144 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-05
Pictures	31
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #19	2024-04-11 10:09
MOT test number	388102679655
Result	✓ Passed
Next expiry date	2025-04-27

MOT #18	2023-04-27 08:50
MOT test number	664181207263
Result	✓ Passed

- Advice** Idler pulley has excessive play
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material All hard brake lines (1.1.11 (c))
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Central Rear Exhaust mounting defective (6.1.2 (a))

MOT #17	2023-04-26 15:20
MOT test number	166813300079
Result	✗ Failed

- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Offside Front Play in steering rack inner joint(s)
- Advice** Central Rear Exhaust mounting defective (6.1.2 (a))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Idler pulley has excessive play
- Advice** Nearside Front Play in steering rack inner joint(s)
- Advice** Brake pipe corroded, covered in grease or other material All hard brake lines (1.1.11 (c))
- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #16	2022-04-28 06:55
MOT test number	732681443936
Result	✓ Passed

MOT #15	2022-04-26 08:23
MOT test number	900986871202
Result	✗ Failed

- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- DANGEROUS** Nearside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- DANGEROUS** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- MAJOR** Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- DANGEROUS** Offside Front Inner Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- MAJOR** Nearside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))

MOT #14	2021-02-08 10:56
MOT test number	245041531139
Result	✓ Passed

- Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #13** 2020-02-06 14:44**MOT test number** 985779003422**Result** ✓ Passed**Advice** Rear Exhaust mounting defective (6.1.2 (a))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #12** 2019-02-05 10:36**MOT test number** 533397803937**Result** ✓ Passed**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))**MOT #11** 2018-01-30 11:54**MOT test number** 850618495040**Result** ✓ Passed**MOT #10** 2017-02-09 09:21**MOT test number** 374106367193**Result** ✓ Passed**MOT #9** 2016-01-18 10:05**MOT test number** 755308203203**Result** ✓ Passed**MOT #8** 2016-01-18 10:05**MOT test number** 652024391604**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)

**MOT #7** 2015-01-12 12:39**MOT test number** 269662515051**Result** ✓ Passed**MOT #6** 2015-01-12 10:12**MOT test number** 559942315034**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2014-01-28 11:26**MOT test number** 937388224035**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-01-18 09:31**MOT test number** 835438413038**Result** ✓ Passed**MOT #3** 2012-07-06 09:57**MOT test number** 926078882174**Result** ✓ Passed**MOT #2** 2011-07-18 16:49**MOT test number** 219549491176**Result** ✓ Passed



MOT #1	2011-02-18 10:52
MOT test number	166429341419
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES-BENZ salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES-BENZ is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-05-30
Last registration	2024-04-11
Complete history	See info



Registration #1	2008-05-30	27 mi
Registration #2	2011-02-18	14.625 mi
Registration #3	2011-07-18	16.256 mi
Registration #4	2012-07-06	20.275 mi
Registration #5	2013-01-18	23.510 mi
Registration #6	2014-01-28	27.661 mi
Registration #7	2015-01-12	30.369 mi
Registration #8	2015-01-12	30.369 mi
Registration #9	2016-01-18	33.787 mi
Registration #10	2016-01-18	33.787 mi
Registration #11	2017-02-09	34.810 mi
Registration #12	2018-05-20	35.277 mi
Registration #13	2019-05-20	35.277 mi
Registration #14	2020-05-20	35.277 mi
Registration #15	2021-05-20	35.277 mi
Registration #16	2022-05-20	35.277 mi
Registration #17	2023-05-20	35.277 mi
Registration #18	2024-05-20	35.277 mi
Registration #19	2025-05-20	35.277 mi
Registration #20	2026-05-20	35.277 mi
Registration #21	2027-05-20	35.277 mi

More info >



Car features

The MERCEDES-BENZ factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MERCEDES-BENZ factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1685 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195531098250