





### General information

Make	VOLVO
Model	S80 D2 SE NAV
Colour	Grey
Year of manufacture	2014
Top speed	115 mph
0 - 60 mph	12.1 seconds
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	115 BHP
Max. torque	270 Nm at 2.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	74.3 mpg
Consumption combined	68.7 mpg
CO2 emission	109 g/km
CO2 label	В







Internet history	
Entry 1	
Date	2021-10-25
Pictures	0
Listing price	View report

source: autotrader.co.uk



## MOT history

MOT expiry date	2024-07-04
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	10
Total items failed	7

MOT #11	2023-07-05 11:40
MOT test number	653829109849
Result	✓ Passed
Next expiry date	2024-07-04

MOT #10	2023-07-04 09:48
MOT test number	379661309543
Result	🗙 Failed
Fail Nearside Side repeater not working (4.4.1 (a) (ii))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
<b>Fail</b> Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))	
<b>Fail</b> Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

МОТ #9	2021-09-20 12:52
MOT test number	157531799100
Result	✓ Passed

MOT #8	2020-11-03 13:48
MOT test number	324569176700
Result	✓ Passed





MOT #7	2020-05-12 15:05
MOT test number	176923632388
Result	✓ Passed
МОТ #6	2019-10-23 10:06
MOT test number	955308108043
Result	✓ Passed

Advice Undercovers fitted

MOT #5		2018-11-02 15:49
MOT test	number	636997437989
Result		✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4		2018-11-02 15:49
MOT test number		646076866771
Result		🗙 Failed
Advice Offside Rear Tyr	e worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Rear Brake pad(	s) wearing thin (1.1.13 (a) (ii))	





MOT #3	2018-09-12 13:42
MOT test number	542532244025
Result	🗙 Failed
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice Offside Rear Tyre worn close to legal limit/worn on edge 1.9mm (5.2.3 (e))	
Fail Exhaust emissions exceed manufacturer's specified limit 0.53 - 1.80 (8.2.2.2 (a))	
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
<b>Fail</b> Exhaust on a vehicle fitted with a diesel particulate filter emits visible smoke of ar (d))	ny colour (8.2.2.2
Fail Offside Front Outer Tyre has ply or cords exposed Sidewall damaged)(225/50/17 (	5.2.3 (d) (ii))

MOT #2	2017-09-28 08:56
MOT test number	161791454800
Result	✓ Passed

MOT #1	2017-04-20 14:33
MOT test number	245661590370
Result	✓ Passed
Advice Front Tyre worn close to the legal limit both (4.1.E.1)	



Tax & MOT check

<b>Tax due:</b> 1 July 2024	✓ Taxed	<b>Expires:</b> 4 July 2024	✓ МОТ
Tax status			Valid until 1 July
Days left			63
MOT expiry date			4 July 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET O
Category	Lamp
Туре	
Domoge 2	AMPLE
Damage 2	C C C C
Date	
Category	AMP
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-12-23
Last registration	2023-07-05
Complete history	See info



Registration #1	2014-12-23	20 mi
Registration #2	2017-04-20	28.610 mi
Registration #3	2017-09-28	30.846 mi
Registration #4	2018-09-12	52.495 mi
Registration #5	2018-11-02	53.302 mi
Registration #6	2018-11-02	53.302 mi
Registration #7	2019-10-23	78.210 mi
Registration #8		11.777 esi
Registration #9		11.777 esi
Registration #10		11.777 esi
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 esi

More info >





### Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



Dimensions & weight	
Width	1861 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1603 kg
Max. allowed weight	2120 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12/12