





General information

| Make CITRO | DEN |
|--------------------------|--------------|
| Model BERLI | INGO HDI XTR |
| Colour Grey | |
| Year of manufacture2011 | |
| op speed107 n | nph |
| 0 - 60 mph 14.3 s | seconds |
| Gearbox 5 spe | ed Manual |

Engine & fuel consumption

| Power | 109 BHP |
|-------------------------|---------------------|
| Max. torque | 240 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.1 mpg |
| Consumption extra urban | 58.9 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | E |





| Internet history | |
|------------------|-------------|
| Entry 1 | |
| Date | 2021-01-29 |
| Pictures | 1 |
| Listing price | View report |



source: autoonline.co.uk



MOT history

| MOT expiry date | 2024-07-01 |
|--------------------|------------|
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 16 |
| Total items failed | 1 |

| MOT #8 | 2020-01-11 10:03 |
|---|---------------------|
| MOT test number | 818444920334 |
| Result | 🗸 Passed |
| Next expiry date | 2021-01-10 |
| Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | |
| Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) | |
| Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakene | d (1.1.14 (a) (ii)) |

| MOT #7 | 2019-01-11 16:29 |
|--|------------------|
| MOT test number | 960267604055 |
| Result | ✓ Passed |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| MOT #6 | 2018-01-30 09:22 |
| MOT test number | 809584535357 |
| Result | ✓ Passed |
| | |

| MOT #5 | 2017-02-17 11:06 |
|-----------------|------------------|
| MOT test number | 370021180457 |
| Result | ✓ Passed |



CV60XPG report date: 2024-03-28

| MOT #4 | | 2016-02-09 12:53 |
|----------|--|------------------|
| MOT test | number | 436473159437 |
| Result | | ✓ Passed |
| | | |
| MOT #3 | | 2015-02-04 14:08 |
| MOT test | number | 335455435050 |
| Result | | ✓ Passed |
| | | |
| MOT #2 | | 2014-02-19 10:48 |
| MOT test | number | 137460854473 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |
| Advice | Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Notice | Vehicle's internal headlight adjuster altered to recheck lights | |
| Advice | Front Brake pad(s) wearing thin (3.5.1g) | |



| CV60XPG |
|-------------------------|
| report date: 2024-03-28 |

| MOT #1 | 2014-02-19 10:48 |
|--|---------------------|
| MOT test number | 377540854001 |
| Result | 🗙 Failed |
| Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Front Brake pad(s) wearing thin (3.5.1g) | |
| Pass with rectification Front Windscreen wiper does not clear the windscreen | effectively (8.2.2) |
| Notice Vehicle's internal headlight adjuster altered to recheck lights | |
| Advice Offside Front Tyre worn close to the legal limit (4.1.E.1) | |
| Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) | |
| Advice Front Tyre worn close to the legal limit (4.1.E.1) | |



Tax & MOT check

| ✓ | ✓ |
|------------------|--------------------|
| Taxed | MOT |
| Tax due: | Expires: |
| 1 July 2024 | 1 July 2024 |
| Tax status | Valid until 1 July |
| Days left | 63 |
| MOT expiry date | 1 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | E |
| Single payment (12 months) | £ 180,00,- |
| Single six month payment | £ 99,00,- |
| Total payable by 12 monthly instalments | £ 189,00,- |





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | |
| Category | Law P |
| Туре | |
| Damage 2 | AMPLE |
| Damage 2 | E CAT D |
| Date | ₩. |
| Category | AMPT |
| Туре | |

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 |





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ****** | |
|--|-------------|
| *********** | |
| ******* | |
| ****** | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this CITROEN had different number plates. | |
| Number of plates | |
| Current registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 9 |
| First mileage registration | 2011-02-02 |
| Last registration | 2020-01-11 |
| Complete history | See info |



| Registration #1 | 2011-02-02 | 20 mi |
|-----------------|------------|------------|
| Registration #2 | 2014-02-19 | 44.394 mi |
| Registration #3 | 2015-02-04 | 57.553 mi |
| Registration #4 | 2016-02-09 | 74.133 mi |
| Registration #5 | 2017-02-17 | 89.489 mi |
| Registration #6 | | 11.117 esi |
| Registration #7 | | 11.177 esi |
| Registration #8 | | 11.177 esi |
| Registration #9 | | 11.777 esi |

More info >



CV60XPG report date: 2024-03-28

Safety ratings

NCAP rating

Video

see crash video



| Dimensions & weight | |
|--|--------------------------|
| Width | 1810 mm |
| Height | 1803 mm |
| Length | 4380 mm |
| Wheel base | 2728 mm |
| Kerb weight | 1426 kg |
| Max. allowed weight | 2065 kg |
| | |
| Additional information | |
| Additional information Fuel tank capacity | 60 I |
| | 60 l Direct Injection |
| Fuel tank capacity | |
| Fuel tank capacity Fuel delivery | Direct Injection |
| Fuel tank capacity Fuel delivery Number of doors | Direct Injection 5 |