





report date: 2024-03-28

General information

Make	ТОҮОТА
Model	URBAN CRUISER D-4D
Colour	Grey
Year of manufacture	2009
Top speed	109 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	205 Nm at 1.800 rpm
Engine capacity	1.364 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2022-06-05

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



Pass with rectification

Pass with rectification

NL59XYD report date: 2024-03-28

MOT history

MOT expiry date	2024-11-11
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	18
Total items failed	2

MOT #15	2023-11-09 17:17
MOT test number	425274530190
Result	✓ Passed
Next expiry date	2024-11-11
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #14	2022-10-19 12:37
MOT test number	183279302526
Result	✓ Passed
MOT #13	2022-10-19 12:37
MOT test number	227577402431
Result	X Failed

Nearside Headlamp aim too high (4.1.2 (a))

Offside Headlamp aim too high (4.1.2 (a))

MOT #12	2021-11-04 15:38
MOT test number	940274893525
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #11 2021-11-03 12:18

MOT test number 958539028094

Result X Failed

MAJOR Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

MAJOR Offside Rear Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))

MOT #10 2020-11-03 16:08

MOT test number 569394609672

Result ✓ Passed

Minor Offside Rear Lower Rear reflector defective or damaged by up to 50% of the reflecting surface in bumper (4.8.1 (a) (i))

Advice Offside Rear rear brake splash guard missing

Advice Nearside Rear rear brake splash guard missing

MOT #9 2020-11-03 09:58

MOT test number 668855007762

Result × Failed

Advice Nearside Rear rear brake splash guard missing

Minor Offside Rear Lower Rear reflector defective or damaged by up to 50% of the reflecting surface in bumper (4.8.1 (a) (i))

MAJOR Offside Rear Inner Brake pipe excessively corroded to flexi (1.1.11 (c))

Advice Offside Rear rear brake splash guard missing

CarCheck.co.uk page 4/13



MOT #8 2019-11-01 11:55

MOT test number 295425433384

Result ✓ Passed

Advice Offside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2018-11-12 09:16

MOT test number 278860667367

Result \(\sqrt{Passed} \)

MOT #6 2017-09-28 10:18

MOT test number 199025761899

Result
✓ Passed

MOT #5 2016-08-27 09:24

MOT test number 521114186175

Result
✓ Passed

MOT #4 2015-09-17 10:57

MOT test number 858763722835

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



MOT #3

MOT test number

Result

MOT #2

MOT test number

2013-09-06 10:50

MOT test number

578909743217

Result

Advice Front registration plate delaminated but not likely to be misread (6.3.1d)

MOT #1	2012-09-12 11:06
MOT test number	308986052423
Result	✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	11 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-


CarCheck.co.uk page 7/13



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

•	
For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r	
MARKET CONTRACTOR CONT	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	100.00.00
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-09-23
Last registration	2023-11-09
Complete history	See info



Registration #1	2009-09-23	27 mi
Registration #2	2012-09-12	10.394 mi
Registration #3	2013-09-06	13.000 mi
Registration #4	2014-09-04	15.961 mi
Registration #5	2015-09-17	23.375 mi
Registration #6	2016-08-27	30.010 mi
Registration #7	2017-09-28	38.284 mi
Registration #8	2018-11-12	45.624 mi
Registration #9	2019-11-01	52.267 mi
Registration #10		11.117 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 mi
Registration #16		11.777 au

More info >

CarCheck.co.uk page 12/13



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1725 mm
Height	1540 mm
Length	3930 mm
Wheel base	2460 mm
Kerb weight	1265 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	42	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13

Number of axles 2

Engine number 1NT1043092