





report date: 2024-03-29

### General information

Make	FIAT
Model	PUNTO MULTIJET ACTIVE
Colour	Red
Year of manufacture	2011
Top speed	103 mph
0 - 60 mph	13.6 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	75 BHP
Max. torque	190 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	68.9 mpg
CO2 emission	108 g/km
CO2 label	В



CarCheck.co.uk page 1/12



report date: 2024-03-29

## Internet history

Entry 1

Date 2021-09-29

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-11-17
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	5
Total items failed	5

MOT #13	2023-11-13 11:52
MOT test number	142077481491
Result	✓ Passed
Next expiry date	2024-11-17

MOT #12	2023-11-07 14:08
MOT test number	371090460903
Result	<b>×</b> Failed
Fail Horn not working (7.7 (a))	

MOT #11	2022-11-07 10:37
MOT test number	749395441448
Result	<b>✓</b> Passed
MOT #10	2021-10-25 12:54
MOT test number	351218014252
Result	✓ Passed

CarCheck.co.uk page 3/12



(c))

**NL61AMU** 

report date: 2024-03-29

MOT #9 2021-10-23 05:49

**MOT test number** 372806793164

Result X Failed

Fail Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #8 2020-11-18 08:50

MOT test number 352121869863

**Result** ✓ Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7** 2019-08-01 08:46

**MOT test number** 937330858141

**MOT #6** 2019-08-01 08:46

MOT test number 526486056259

**Result** X Failed

Pass with rectification Offside Rear Seat belt not functioning as intended Rectified time of test (7.1.2

**MOT #5** 2018-07-25 09:13

MOT test number 249626669031

**Result** 
✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4	2018-07-16 10:14
MOT test number	739321270648
Result	<b>×</b> Failed
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))			
MOT #3	2017-07-19 09:26		
MOT test number	222571474268		
Result	✓ Passed		
MOT #2	2016-04-27 07:23		
MOT test number	990963117102		
Result	✓ Passed		
MOT #1	2014-08-07 09:45		
MOT test number	996229714218		
Result	✓ Passed		

CarCheck.co.uk page 5/12



NL61AMU report date: 2024-03-29

### Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	17 November 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Ow		la : -	
( )\//	ner	nis	

For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
manage of the same	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK OK
Plate since	
Current registration	UK NAME OF THE PROPERTY OF THE
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-08
Last registration	2023-11-13
Complete history	See info



Registration #1	2011-09-08	26 mi
Registration #2	2014-08-07	10.888 mi
Registration #3	2016-04-27	13.423 mi
Registration #4	2017-07-19	14.185 mi
Registration #5	2018-07-16	14.742 mi
Registration #6	2018-07-25	14.752 mi
Registration #7	2019-08-01	14.933 mi
Registration #8	2019-08-01	14.933 mi
Registration #9		11.777 es
Registration #10		77,777 46
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 ms

More info >

CarCheck.co.uk page 11/12



NL61AMU report date: 2024-03-29

# Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1665 kg

# Additional information

Fuel tank capacity	45 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 4294856