



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO MATCH EDITION TDI
Colour	White
Year of manufacture	2013
Top speed	105 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	180 Nm at 2.000 rpm
Engine capacity	1.199 cc
Cylinders	3
Fuel type	Diesel
Consumption city	58.9 mpg
Consumption extra urban	83.1 mpg
Consumption combined	72.4 mpg
CO2 emission	102 g/km
CO2 label	B





## MOT history

MOT expiry date	2024-11-17
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	20
Total items failed	4

**MOT #11** 2023-11-18 10:39**MOT test number** 674942300656**Result** ✓ Passed**Next expiry date** 2024-11-17**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2022-11-18 15:01**MOT test number** 591015296222**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #9** 2022-11-18 15:01**MOT test number** 113453932845**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))



**MOT #8** 2021-08-30 11:37**MOT test number** 346073706675**Result** ✓ Passed**Advice** Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**MOT #7** 2020-08-26 07:48**MOT test number** 766181329005**Result** ✓ Passed**MOT #6** 2019-08-07 14:32**MOT test number** 501172002361**Result** ✓ Passed**MOT #5** 2018-08-14 08:10**MOT test number** 137346430692**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge bold inside edge (5.2.3 (e))**MOT #4** 2018-08-13 14:43**MOT test number** 265384992277**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge bold inside edge (5.2.3 (e))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

**MOT #3** 2017-08-24 13:03**MOT test number** 704065372363**Result** ✓ Passed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2017-08-24 09:14**MOT test number** 290588603366**Result** ✗ Failed

- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #1** 2016-08-31 13:35**MOT test number** 354151708460**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
17 November 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	17 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	B
<b>Single payment (12 months)</b>	£ 20,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	<b>FN63JWU</b>
Plate since	2019-06-29
Current registration	<b>FN63JWU</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-09-01
Last registration	2023-11-18
Complete history	<a href="#">See info</a>



Registration #1	2013-09-01	26 mi
Registration #2	2016-08-31	33.049 mi
Registration #3	2017-08-24	44.244 mi
Registration #4	2017-08-24	44.245 mi
Registration #5	2018-08-13	54.886 mi
Registration #6	2018-08-14	54.886 mi
Registration #7	2019-08-13	65.527 mi
Registration #8	2019-08-13	65.527 mi
Registration #9	2019-08-13	65.527 mi
Registration #10	2019-08-13	65.527 mi
Registration #11	2019-08-13	65.527 mi
Registration #12	2019-08-13	65.527 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1682 mm
Height	1462 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1134 kg
Max. allowed weight	1620 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Engine number	CFWA366345